

Photographs of Hindmans Way, Dagenham Dock (taken 4 Feb. 2019)



Pic. 1: The footpath in Hindmans Way (seen on the left of the picture) currently ends abruptly, with no safe crossing for pedestrians or cyclists.



Pic. 2: Land on right of picture was transferred to GLAP's predecessor in title for the purpose of constructing Hindmans Way to an adoptable standard.



Pic 3.: BT chamber at end of the northern section of Hindmans Way. A road realignment (from this point) is required to ensure adequate space on both sides of the new highway for the footway / cycle path to avoid an existing building.