

SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Workshop Garages External corrugated roof sheet	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Cement	Quantity 60m ²	Sample No Survey Date Date of Report Surveyor(s)	As 06/B/8026/126 24.04 - 29.06.06 18.08.06

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Workshop Garages Internal cladding panels	Asbestos Yes Type Chrysotile (White)
Material Type Cement	Quantity 50m ²	Sample No 06/B/8026/129 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) XXXXXXXXXX	

Photograph



SURVEY INFORMATION SHEET



Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Maintenance workshop External corrugated roof sheet	Asbestos Yes, Strongly Presumed	Type Chrysotile (White)
Material Type Cement	Quantity 20m ²	Sample No As 06/B/8026/126	
		Survey Date 24.04 - 29.06.06	
		Date of Report 18.08.06	
		Surveyor(s) 	

Photograph



SURVEY INFORMATION SHEET


Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Barn Roof End Gable Upstand panels		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	10m ²	Sample No	As 06/B/8026/126
				Survey Date	24.04 – 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	[REDACTED]



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo External Bin Stores adjacent Zachary York Ward Corrugated Roof sheet		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	20m	Sample No	As 06/B/8026/126
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo External Bin Stores adjacent Zachary York Ward Gaskets	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Gasket	Quantity	<1m ²	Sample No As 06/B/8026/180 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Nightingale Ward

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Nightingale Ward Room adjacent corridor/lobby Rope to low level pipes	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Rope	Quantity <1m	Sample No Survey Date Date of Report Surveyor(s)	As 06/B/8026/58 24.04 - 29.06.06 18.08.06

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Nightingale Ward Kitchen Rope to pipework		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	1m	Sample No	As 06/B/8026/58
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Nightingale Ward Kitchen Sink paint		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Bitumen		Quantity 1m ²		Sample No	As 06/B/8026/157
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Nightingale Ward First floor window infill panels	Asbestos Yes
Material Type Board		Quantity <1m ²	Type Amosite (Brown) Chrysotile (White)
			Sample No 06/B/8026/130
			Survey Date 24.04 - 29.06.06
			Date of Report 18.08.06
			Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulson, Surrey, CR5 3ES		Position of Sample/Photo Nightingale Ward Cistern W.C (X6)		Asbestos	Yes, Strongly Presumed
Material Type Plastic		Quantity 1m ²		Type	Amosite (Brown)
				Sample No	As 06/B/8026/5
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulson, Surrey, CR5 3ES		Position of Sample/Photo Nightingale Ward Undercroft Debris (presumed throughout)		Asbestos Type	Yes Crocidolite (Blue) Amosite (Brown) Chrysotile (White)
Material Type	Lagging	Quantity	<1m ²	Sample No	06/B/8026/131
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Hall adjacent Nightingale Ward Skylight rope seal		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	10m	Sample No	As 06/B/8026/31
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Hall adjacent Nightingale Ward Skylight rope seal		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	20m	Sample No	As 06/B/8026/31
				Survey Date	24.04 – 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Workshops

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Workshop stores adjacent Hall Pipe Lagging	Asbestos Yes	
		Type Amosite (Brown)	
Material Type Lagging	Quantity 10m	Sample No 06/B/8026/132	
		Survey Date 24.04 - 29.06.06	
		Date of Report 18.08.06	
		Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Workshop stores adjacent Hall Cement workbench (X2) adjacent sink	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	2m ²	Sample No As 06/B/8026/158
				Survey Date 24.04 - 29.06.06
				Date of Report 18.08.06
				Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Workshop stores adjacent Hall Low level boxing	<table style="width: 100%;"> <tr> <td style="width: 30%;">Asbestos</td> <td>Yes, Strongly Presumed</td> </tr> <tr> <td>Type</td> <td>Chrysotile (White)</td> </tr> </table>	Asbestos	Yes, Strongly Presumed	Type	Chrysotile (White)								
Asbestos	Yes, Strongly Presumed													
Type	Chrysotile (White)													
<table style="width: 100%;"> <tr> <td style="width: 30%;">Material Type</td> <td>Cement</td> </tr> </table>	Material Type	Cement	<table style="width: 100%;"> <tr> <td style="width: 30%;">Quantity</td> <td>1m²</td> </tr> </table>	Quantity	1m ²	<table style="width: 100%;"> <tr> <td style="width: 30%;">Sample No</td> <td>As 06/B/8026/78</td> </tr> <tr> <td>Survey Date</td> <td>24.04 - 29.06.06</td> </tr> <tr> <td>Date of Report</td> <td>18.08.06</td> </tr> <tr> <td>Surveyor(s)</td> <td style="background-color: black; color: black;">[REDACTED]</td> </tr> </table>	Sample No	As 06/B/8026/78	Survey Date	24.04 - 29.06.06	Date of Report	18.08.06	Surveyor(s)	[REDACTED]
Material Type	Cement													
Quantity	1m ²													
Sample No	As 06/B/8026/78													
Survey Date	24.04 - 29.06.06													
Date of Report	18.08.06													
Surveyor(s)	[REDACTED]													

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Workshop stores adjacent Hall Pipe Lagging	Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type	Lagging	Quantity	10m	Sample No As 06/B/8026/132
				Survey Date 24.04 - 29.06.06
				Date of Report 18.08.06
				Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Workshop stores adjacent Hall Pipe Lagging		Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type	Lagging	Quantity	10m	Sample No	As 06/B/8026/132
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Workshop stores adjacent Hall Pipe Lagging		Asbestos Type	Yes, Strongly presumed Amosite (Brown)
Material Type	Lagging	Quantity	10m	Sample No	As 06/B/8026/132
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Derelict Corridor adjacent stores Electrics		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	1m ²	Sample No	As 06/B/8026/22
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Derelict Corridor adjacent workshop WC Cistern		Asbestos	Yes, Strongly Presumed
Material Type Plastic		Quantity 1m ²		Type	Amosite (Brown)
				Sample No	As 06/B/8026/5
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Donne/Dickens Ward Electrics Flashguards		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	1m	Sample No	As 06/B/8026/9
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Donne/Dickens Ward Kitchen sink		Asbestos	Yes, Strongly Presumed
				Type	Chrysotile (White)
Material Type	Bitumen	Quantity	1m ²	Sample No	As 06/B/8026/157
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Donne/Dickens Ward Ground Floor WC Cistern (X2)		Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type Plastic		Quantity 1m ²		Sample No Survey Date Date of Report Surveyor(s)	As 06/B/8026/5 24.04 - 29.06.06 18.08.06 [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Donne/Dickens Ward Ground Floor Kitchen Sink paint		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Bitumen		Quantity 1m ²		Sample No Survey Date Date of Report Surveyor(s)	As 06/B/8026/157 24.04 - 29.06.06 18.08.06 [REDACTED]


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Donne/Dickens Ward First floor Kitchen Rope to pipe		Asbestos Yes, Strongly Presumed
Material Type Rope		Quantity <1m ²		Type Chrysotile (White)
				Sample No As 06/B/8026/58
				Survey Date 24.04 - 29.06.06
				Date of Report 18.08.06
				Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Donne/Dickens Ward First Floor WC Cistern (X2)	Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type	Plastic	Quantity	1m ²	Sample No As 06/B/8026/5 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s)

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Donne/Dickens Ward First Floor Kitchen Sink paint	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Bitumen	Quantity 1m ²	Sample No As 06/B/8026/157 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Donne/Dickens Ward Electrics (X2) rope seal		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	1m	Sample No	As 06/B/8026/22
				Survey Date	24.04 – 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Faraday Ward & Plant Room adjacent Faraday Ward

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Calorifier Room adjacent Faraday Ward Large Tanks Pipe Lagging	<table style="width: 100%;"> <tr> <td style="width: 50%;">Asbestos</td> <td>Yes</td> </tr> <tr> <td>Type</td> <td>Amosite (Brown) Chrysotile (White)</td> </tr> </table>	Asbestos	Yes	Type	Amosite (Brown) Chrysotile (White)				
Asbestos	Yes									
Type	Amosite (Brown) Chrysotile (White)									
Material Type Lagging	Quantity 200m In total	<table style="width: 100%;"> <tr> <td style="width: 50%;">Sample No</td> <td>06/B/8026/133</td> </tr> <tr> <td>Survey Date</td> <td>24.04 - 29.06.06</td> </tr> <tr> <td>Date of Report</td> <td>18.08.06</td> </tr> <tr> <td>Surveyor(s)</td> <td style="background-color: black; color: black;">[REDACTED]</td> </tr> </table>	Sample No	06/B/8026/133	Survey Date	24.04 - 29.06.06	Date of Report	18.08.06	Surveyor(s)	[REDACTED]
Sample No	06/B/8026/133									
Survey Date	24.04 - 29.06.06									
Date of Report	18.08.06									
Surveyor(s)	[REDACTED]									

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Calorifier Room adjacent Faraday Ward Pipe Lagging Debris	Asbestos Type	Yes, Strongly Presumed Amosite (Brown) Chrysotile (White)
Material Type	Lagging	Quantity	1m ²	Sample No As 06/B/8026/133 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Calorifier Room adjacent Faraday Ward Small Tank & Pipe Lagging		Asbestos Type	Yes, Strongly Presumed Amosite (Brown) Chrysotile (White)
Material Type	Lagging	Quantity	200m In total	Sample No	As 06/B/8026/133
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Calorifier Room adjacent Faraday Ward Gaiter (X2)		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Rope	Quantity 1m ²	Sample No		As 06/B/8026/72	
		Survey Date		24.04 - 29.06.06	
		Date of Report		18.08.06	
		Surveyor(s)		[REDACTED]	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Calorifier Room adjacent Faraday Ward External Roof Soffitt		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	10m	Sample No	06/B/8026/134
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Corridor adjacent Faraday Ward Skylight rope seal		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Rope		Quantity 10m		Sample No	As 06/B/8026/31
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Faraday Ward Lobby Wall electrics Rope Seals	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Rope	Quantity 1m	Sample No As 06/B/8026/22 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Faraday Ward Ground Floor Kitchen Rope to pipework		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	1m ²	Sample No	As 06/B/8026/58
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Faraday Ward Ground floor kitchen Sink paint		Asbestos	None Detected
Material Type Bitumen		Quantity 1m ²		Type	N/A
				Sample No	06/B/8026/135
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Faraday Ward Ground Floor W.C. Cistern (X20)	Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type	Plastic	Quantity	1m ² each	Sample No Survey Date Date of Report Surveyor(s)
				As 06/B/8026/5 24.04 - 29.06.06 18.08.06 [REDACTED]


Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Faraday Ward Riser rawl plugs (presumed throughout)	Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type	Board	Quantity	<1m	Sample No As 06/B/8026/65 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Faraday Ward Ground Floor Nurses Station stud walls Internal Sandwich Boards	Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type	Board	Quantity	20m ²	Sample No Survey Date Date of Report Surveyor(s)
				As 06/B/8026/78 24.04 - 29.06.06 18.08.06 

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Faraday Ward Skylight Rope seal	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Rope	Quantity 20m	Sample No As 06/B/8026/31 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Faraday Ward First Floor, Main Ward Fireplace panels & debris		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Cement		Quantity 1m ²		Sample No	As 06/B/8026/19
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Faraday Ward End Office Fireplace panels & debris	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Cement	Quantity 1m ²	Sample No As 06/B/8026/19 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Faraday Ward Office Fireplace panels & debris		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Cement		Quantity 1m ²		Sample No	As 06/B/8026/19
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Faraday Ward Room adjacent Ward Wall electrics		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	100m	Sample No	As 06/B/8026/28
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulson, Surrey, CR5 3ES		Position of Sample/Photo Faraday Ward Office adjacent stairs Fireplace panels		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	1m ²	Sample No	As 06/B/8026/19
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Faraday Ward Second Floor Sink Pad		Asbestos	Yes, Strongly Presumed
				Type	Chrysotile (White)
Material Type	Bitumen	Quantity	1m ²	Sample No	As 06/B/8026/64
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	[REDACTED]


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulson, Surrey, CR5 3ES		Position of Sample/Photo Guy Ward First Floor Kitchen Sink Paint		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Bitumen		Quantity <1m ²		Sample No Survey Date Date of Report Surveyor(s)	As 06/B/8026/157 24.04 – 29.06.06 18.08.06 


Photograph



SURVEY INFORMATION SHEET

Location of Survey		Position of Sample/Photo		Asbestos	Yes
Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Guy Ward Undercroft Lagging debris		Type	Amosite (Brown)
Material Type	Lagging	Quantity	<1m	Sample No	06/B/8026/136
				Survey Date	24.04 – 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Roof felt, outhouse adj to Guy ward	Asbestos None Detected Type N/A)
Material Type Felt	Quantity 1m ²	Sample No 06/B/8026/142 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Damp course, outhouse adj to Guy ward	Asbestos None Detected Type N/A
Material Type Bitumen	Quantity 10m	Sample No 06/B/8026/143 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Harvard Ward

Location of Survey		Position of Sample/Photo	Asbestos	None Detected
Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Harvard Ward Lagging to RH external pipe leading to undercroft,	Type	N/A
Material Type	Lagging	Quantity 20m ²	Sample No	06/B/8026/137
			Survey Date	24.04 - 29.06.06
			Date of Report	18.08.06
			Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Harvard Ward Lagging to LH external pipe leading to undercroft	Asbestos Type	None Detected N/A
Material Type	Lagging	Quantity	10m ²	Sample No 06/B/8026/138 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Harvard Ward W.C. Cistern (X27)		Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type	Plastic	Quantity	1m ² each	Sample No	As 06/B/8026/5
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Harvard Ward Link corridor to W.C Block Wall mounted iron pad		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	<1m ²	Sample No	As 06/B/8026/20
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Harvard ward Textured coating to support pillar		Asbestos Type	None Detected N/A
Material Type	Textured Coating	Quantity	4m ²	Sample No	06/B/8026/139
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Harvard Ward Lobby Wall electrics Rope Seals		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	1m	Sample No	As 06/B/8026/22
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Harvard Ward Ground Floor Kitchen Rope to pipework		Asbestos Type	Yes., Strongly Presumed Chrysotile (White)
Material Type Rope		Quantity 1m ²		Sample No	As 06/B/8026/58
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Harvard Ward Room opposite kitchen Sink Pad		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Bitumen	Quantity	<1m ²	Sample No	As 06/B/8026/64
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Harvard ward Pipe residue, corridor undercroft		Asbestos Type	None Detected N/A
Material Type Lagging		Quantity 10m	Sample No 06/B/8026/140		
			Survey Date 24.04 - 29.06.06		
			Date of Report 18.08.06		
			Surveyor(s) [REDACTED]		

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Harvard Ward First Floor Kitchen Rope to pipe work		Asbestos	Yes, Strongly Presumed
Material Type		Quantity		Type	Chrysotile (White)
Rope		1m		Sample No	As 06/B/8026/58
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Harvard ward Lift motor room Panel to hatch	Asbestos Yes
Material Type Board		Quantity 1m ²	Type Amosite (Brown) Chrysotile (White)
			Sample No 06/B/8026/145
			Survey Date 24.04 - 29.06.06
			Date of Report 18.08.06
			Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Rooms adjacent link corridor & Harvard Ward W.C. Cistern		Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type Plastic		Quantity 1m		Sample No Survey Date Date of Report Surveyor(s)	As 06/B/8026/5 24.04 - 29.06.06 18.08.06 

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Rooms adjacent link corridor & Harvard Ward Fireplace panel	Asbestos Type	Yes, Strongly presumed Chrysotile (White)
Material Type	Cement	Quantity	1m	Sample No As 06/B/8026/19
				Survey Date 24.04 - 29.06.06
				Date of Report 18.08.06
				Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Rooms adjacent link corridor & Harvard Ward Sink Pad		Asbestos	Yes, Strongly Presumed
				Type	Chrysotile (White)
Material Type	Bitumen	Quantity	1m ²	Sample No	As 06/B/8026/64
				Survey Date	24.04 – 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Kings Keats Ward

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES	Position of Sample/Photo Kings Keats Ward W.C. Cistern (X20)	Asbestos Yes, Strongly Presumed Type Amosite (Brown)
Material Type Plastic	Quantity 1m ² Each	Sample No As 06/B/8026/5 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Kings Keats Ward Kitchen Rope to pipework		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	1m ²	Sample No	As 06/B/8026/58
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Kings Keats Ward Sink Paint		Asbestos	Yes, Strongly Presumed
Material Type Bitumen		Quantity 1m ²		Type	Chrysotile (White)
				Sample No	As 06/B/8026/157
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Kings Keats Ward Wall Electrics Rope seals		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	1m	Sample No	As 06/B/8026/22
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Kings Keats Ward Sink Pad		Asbestos Yes, Strongly Presumed
Material Type Bitumen		Quantity 1m ²		Type Chrysotile (White)
				Sample No As 06/B/8026/64
				Survey Date 24.04 - 29.06.06
				Date of Report 18.08.06
				Surveyor(s) [REDACTED]


Photograph



SURVEY INFORMATION SHEET


Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Panel to hatch, lift motor room, King Keats ward		Asbestos Type	None Detected N/A
Material Type	Board	Quantity	<1m ²	Sample No	06/B/8026/144
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Johnson/Jenner Ward and Plant Room adjacent Johnson Ward

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Johnson/Jenner Ward Textured coating to support pillar	Asbestos Type	None Detected N/A
Material Type	Textured coating	Quantity	4m ²	Sample No 06/B/8026/146 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) 

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Johnson/Jenner Ward Ground Floor Upstand to skylight roof in sun room	Asbestos Yes Type Chrysotile (White)
Material Type Cement	Quantity 1m	Sample No 06/B/8026/147 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Johnson/Jenner Ward Sun Room Skylight Rope Seal	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	200m	Sample No As 06/B/8026/31 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Johnson/Jenner Ward Ceiling panels to sun room,	Asbestos Yes Type Chrysotile (White)
Material Type Cement	Quantity 10m ²	Sample No 06/B/8026/148 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Johnson/Jenner Ward Wall Electrics		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	1m	Sample No	As 06/B/8026/9
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Johnson/Jenner Ward Kitchen Rope to pipe work	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Rope	Quantity 1m	Sample No As 06/B/8026/58 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]	


Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Johnson/Jenner Ward First Floor Sink Paint		Asbestos	Yes, Strongly Presumed
				Type	Chrysotile (White)
Material Type	Bitumen	Quantity	1m	Sample No	As 06/B/8026/157
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Johnson/Jenner Ward First Floor Sun Room Skylight Rope Seal		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	100m	Sample No	As 06/B/8026/31
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Johnson/Jenner Ward First Floor Sink Pad		Asbestos	Yes, Strongly Presumed
Material Type Bitumen		Quantity 1m ²		Type	Chrysotile (White)
				Sample No	As 06/B/8026/64
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Johnson/Jenner Ward First Floor Kitchen Rope to pipe work		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	1m	Sample No	As 06/B/8026/58
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Johnson/Jenner Ward First Floor Kitchen Sink Paint		Asbestos	Yes, Strongly Presumed
				Type	Chrysotile (White)
Material Type Bitumen		Quantity 1m		Sample No	As 06/B/8026/157
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Boiler House adjacent to Johnson/Jenner Ward Large Tank (X3) Lagging		Asbestos Type	Yes, Strongly Presumed Amosite (Brown) Chrysotile (White)
Material Type	Lagging	Quantity	120m ²	Sample No	As 06/B/8026/150
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Boiler House adjacent to Johnson/Jenner Ward Small Tank Lagging		Asbestos Type	Yes, Strongly Presumed Amosite (Brown) Chrysotile (White)
Material Type	Lagging	Quantity	60m ²	Sample No	As 06/B/8026/150
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Boiler House adjacent to Johnson/Jenner Ward Lagging debris on floor	Asbestos Yes Type Amosite (Brown) Chrysotile (White)
Material Lagging Type	Quantity Debris	Sample No 06/B/8026/150 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Boiler House adjacent to Johnson /Jenner Ward Electrics	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope & Cement	Quantity	2m	Sample No As 06/B/8026/9 & 22 & 28 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Boiler block adjacent Johnson/Jenner Ward Door Panel	<table style="width: 100%;"> <tr> <td style="width: 50%;">Asbestos</td> <td>Yes</td> </tr> <tr> <td>Type</td> <td>Amosite (Brown) Chrysotile (White)</td> </tr> </table>	Asbestos	Yes	Type	Amosite (Brown) Chrysotile (White)				
Asbestos	Yes									
Type	Amosite (Brown) Chrysotile (White)									
Material Type Board	Quantity 4m ²	<table style="width: 100%;"> <tr> <td style="width: 50%;">Sample No</td> <td>06/B/8026/151</td> </tr> <tr> <td>Survey Date</td> <td>24.04 - 29.06.06</td> </tr> <tr> <td>Date of Report</td> <td>18.08.06</td> </tr> <tr> <td>Surveyor(s)</td> <td style="background-color: black; color: black;">[REDACTED]</td> </tr> </table>	Sample No	06/B/8026/151	Survey Date	24.04 - 29.06.06	Date of Report	18.08.06	Surveyor(s)	[REDACTED]
Sample No	06/B/8026/151									
Survey Date	24.04 - 29.06.06									
Date of Report	18.08.06									
Surveyor(s)	[REDACTED]									

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Boiler Block adjacent Johnson/Jenner Ward Red Pipe lagging	Asbestos Yes, Strongly Presumed Type Amosite (Brown)
Material Type Lagging	Quantity 100m	Sample No 06/B/8026/152 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Boiler Block adjacent Johnson/Jenner Ward Pipes entering duct	Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type Lagging	Quantity 10m	Sample No Survey Date Date of Report Surveyor(s)	As 06/B/8026/152 24.04 – 29.06.06 18.08.06

Photograph




SURVEY INFORMATION SHEET

Nurses Staff Wing

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Nurses Block adjacent King/Keats Ward Panels in loft(x12)	Asbestos Yes Type Amosite (Brown)
Material Type Board	Quantity 60m ²	Sample No 06/B/8026/153 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulson, Surrey, CR5 3ES		Position of Sample/Photo Nurse Block Staff Wing W.C. Cistern (X11)		Asbestos	Yes, Strongly Presumed
Material Type Plastic		Quantity 1m ² each		Type	Amosite (Brown)
				Sample No	As 06/B/8026/5
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Nurse Block Sink Pad (X6)	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Bitumen	Quantity	<1m ²	Sample No As 06/B/8026/64 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s)
				

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Nurses Block adjacent King/ Keats Ward Flue pipe & Cement sheet in bunny boiler, (to all floors X3)		Asbestos Type	Yes Chrysotile (White)
Material Type	Cement	Quantity	2m ² (X3)	Sample No	06/B/8026/154
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Nurses Block External Flue pipe	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	8m	Sample No As 06/B/8026/154 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Kings/Keats Link Corridor Floor Tiles		Asbestos Type	Yes, Strongly presumed Chrysotile (White)
Material Type	Vinyl	Quantity	120m	Sample No	As 06/B/8026/99
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Nurses Wing Link Corridor Floor Tiles	Asbestos Yes, Strongly presumed Type Chrysotile (White)
Material Type Vinyl	Quantity 60m ²	Sample No As 06/B/8026/100 Survey Date 24.04 – 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Lidgett/Lettsom Ward

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Lidgett/Lettsom Ward Electrics		Asbestos Type	Yes, Strongly presumed Chrysotile (White)
Material Type Rope		Quantity 1m ²		Sample No	As 06/B/8026/22
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Lidgett/Lettsom Ward Riser Rope lagging to pipe		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Rope		Quantity 4m		Sample No	As 06/B/8026/58
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Lidgett/Lettsom Ward W.C. Cistern		Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type	Plastic	Quantity	1m ²	Sample No	As 06/B/8026/5
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Lidgett/Lettsom Ward Bathroom Floor Tile	Asbestos Yes, Strongly presumed Type Chrysotile (White)
Material Type Vinyl	Quantity 24m	Sample No As 06/B/8026/63 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Lidgett/Lettsom Ward Kitchen rope debris		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	<1m ²	Sample No	As 06/B/8026/58
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Lidgett/Lettsom Ward Paper insert to pipe lagging, undercroft (presumed throughout)		Asbestos Yes
Material Type Paper		Quantity 1m ²		Type Chrysotile (White)
				Sample No 06/B/8026/155
				Survey Date 24.04 - 29.06.06
				Date of Report 18.08.06
				Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Ledgitt/Lettsom Ward Textured coating to pillars, 1 st floor,	Asbestos Type	None Detected N/A
Material Type	Textured coating	Quantity	1m ²	Sample No 06/B/8026/156 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Lidgett/Lettsom Ward Kitchen Sink Paint	Asbestos Yes
			Type Chrysotile (White)
Material Type Bitumen	Quantity 1m ²	Sample No 06/B/8026/157	
		Survey Date 24.04 - 29.06.06	
		Date of Report 18.08.06	
		Surveyor(s) 	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Lidgitt/Lettsom Ward Loft, Pipe lagging adjacent tank	Asbestos Yes Type Chrysotile (White) Crocidolite (Blue)	
Material Type Lagging	Quantity 1m ²	Sample No 06/B/8026/226 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulson, Surrey, CR5 3ES		Position of Sample/Photo Lidgitt/Lettsom Ward, Loft, Pipe lagging	Asbestos Type	Yes, Strongly Presumed Chrysotile (White) Crocidolite (Blue)
Material Type	Lagging	Quantity	100m	Sample No As 06/B/8026/226 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Lidgitt/Lettsom Ward Loft, Pipe lagging debris		Asbestos Type	Yes, Strongly Presumed Chrysotile (White) Crocidolite (Blue)
Material Type	Lagging	Quantity	<1m	Sample No	As 06/B/8026/226
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Art Therapy, Canteen and Kitchens

Location of Survey Cane Hill Hospital, Cane Hill, Coulson, Surrey, CR5 3ES	Position of Sample/Photo Art Therapy Flue pipe adjacent boxing	Asbestos Yes, Strongly presumed Type Chrysotile (White)
Material Type Cement	Quantity 2m	Sample No As 06/B/8026/154 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Art Therapy WC adjacent Corridor Bunny Boiler & Flue pipe		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	1m	Sample No	As 06/B/8026/154
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Art Therapy Kitchen Cement panel under sideboard	Asbestos Yes Type Chrysotile (White)
Material Type Cement	Quantity 2m	Sample No 06/B/8026/158 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Art Therapy Skylight (X4) Rope seal		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	40m	Sample No	As 06/B/8026/31
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Art Therapy Kitchen Rope to Pipe		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Rope		Quantity <1m		Sample No	As 06/B/8026/58
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Art Therapy External flue pipe	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	<1m ²	Sample No As 06/B/8026/154 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Art Therapy W.C. Cistern (X3)	Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type	Plastic	Quantity	1m	Sample No As 06/B/8026/5 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Art Therapy First Floor end of Corridor Bathroom Bunny Boiler & Flue pipe		Asbestos	Yes, Strongly Presumed
				Type	Chrysotile (White)
Material Type	Cement	Quantity	1m	Sample No	As 06/B/8026/154
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	[REDACTED]


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulson, Surrey, CR5 3ES		Position of Sample/Photo Canteen Undercroft Foil paper lagging,		Asbestos Yes
Material Type Paper		Quantity 3m		Type Chrysotile (White)
		Sample No 06/B/8026/159		
		Survey Date 24.04 - 29.06.06		
		Date of Report 18.08.06		
		Surveyor(s) [REDACTED]		

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Canteen Undercroft Foil paper lagging debris		Asbestos Type	Yes, Strongly presumed Chrysotile (White)
Material Type	Paper	Quantity	<1m	Sample No	As 06/B/8026/159
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Canteen Electrics		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Rope		Quantity 1m ²		Sample No	As 06/B/8026/9
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Canteen Wall electrics	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Rope	Quantity <1m ²	Sample No As 06/B/8026/22 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]		

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Hall adjacent Canteen Skylight rope seal		Asbestos	Yes, Strongly Presumed
Material Type Rope		Quantity 40m		Type	Chrysotile (White)
				Sample No	As 06/B/8026/31
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Canteen, Catering Hall Radiator panel (X6)	Asbestos Yes
Material Type Cement		Quantity 6m ²	Type Chrysotile (White)
			Sample No 06/B/8026/160
			Survey Date 24.04 - 29.06.06
			Date of Report 18.08.06
			Surveyor(s) 


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Kitchen adjacent Catering Hall Sink paint	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Bitumen	Quantity	1m	Sample No Survey Date Date of Report Surveyor(s)
				As 06/B/8026/157 24.04 - 29.06.06 18.08.06 [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Catering department W.C. Cistern		Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type	Plastic	Quantity	1m ²	Sample No	As 06/B/8026/5
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Catering Hall Skylight rope seal		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Rope		Quantity 30m		Sample No	As 06/B/8026/31
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Understairs WC adjacent Main Hall W.C. Cistern		Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type	Plastic	Quantity	1m ²	Sample No As 06/B/8026/5 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Understairs WC adjacent Main Hall Bunny Boiler & Flue pipe		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Cement		Quantity 2m		Sample No	As 06/B/8026/154
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Kitchen Skylight Rope Seals	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	<1m ²	Sample No As 06/B/8026/31
				Survey Date 24.04 - 29.06.06
				Date of Report 18.08.06
			Surveyor(s)	

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Kitchen Electrics Rope Seals		Asbestos Type	Yes, Strongly presumed Chrysotile (White)
Material Type Rope		Quantity 1m ²		Sample No	As 06/B/8026/22
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Kitchen Cement to fridge wall		Asbestos Yes
Material Type Cement		Quantity 40m ²	Type Chrysotile (White)	
		Sample No 06/B/8026/161		
		Survey Date 24.04 - 29.06.06		
		Date of Report 18.08.06		
		Surveyor(s) 		

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Kitchen Hall Roof guttering		Asbestos Yes
Material Type Cement		Quantity 20m ²		Type Chrysotile (White)
				Sample No 06/B/8026/162
				Survey Date 24.04 - 29.06.06
				Date of Report 18.08.06
				Surveyor(s) [REDACTED]

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Kitchen Electrics Rope Seals	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Rope	Quantity <1m	Sample No As 06/B/8026/22 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulson, Surrey, CR5 3ES		Position of Sample/Photo Kitchen W.C Cistern		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Plastic	Quantity	1m ²	Sample No	As 06/B/8026/5
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Kitchen Electrics in wood boxing		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	1m	Sample No	As 06/B/8026/9
				Survey Date	24.04 – 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Laundry and Workshops

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Laundry Office Wall Panel		Asbestos	Yes
Material Type Cement		Quantity 12m ²		Type	Chrysotile (White)
				Sample No	06/B/8026/163
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Laundry office Panel partition to store		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Cement		Quantity 4m ²		Sample No	As 06/B/8026/163
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Laundry Skylight rope seals	Asbestos Yes, Strongly Presumed Type Chrysotile (White)
Material Type Rope	Quantity 80m	Sample No As 06/B/8026/31 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Laundry Electrics		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	1m ²	Sample No	As 06/B/8026/22
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Laundry Small Office in Main Room Foil paper lagging	Asbestos Yes Type Chrysotile (White)
Material Type Paper	Quantity 8m	Sample No 06/B/8026/164 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Laundry Toilets Paper under MMMF lagging (presumed throughout)	Asbestos Type	Yes Chrysotile (White)
Material Type Paper	Quantity 1000m ²	Sample No	06/B/8026/165
		Survey Date	24.04 - 29.06.06
		Date of Report	18.08.06
		Surveyor(s)	[REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Laundry Toilets Bunny boiler & Flue pipe		Asbestos Type	Yes, Strongly presumed Chrysotile (White)
Material Type Cement		Quantity 1m ²	Sample No As 06/B/8026/154		
			Survey Date 24.04 - 29.06.06		
			Date of Report 18.08.06		
			Surveyor(s) [REDACTED]		

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Laundry WC, Window infill panel above boiler	Asbestos Yes Type Amosite (Brown)	
Material Type Board	Quantity <1m	Sample No 06/B/8026/166 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Laundry Main Room Red pipe lagging		Asbestos Yes
Material Type Lagging		Quantity 2m		Type Chrysotile (White) Amosite (Brown)
				Sample No 06/B/8026/167
				Survey Date 24.04 - 29.06.06
				Date of Report 18.08.06
				Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Laundry Main Room Wall debris	Asbestos Yes Type Chrysotile (White)
Material Type Lagging	Quantity <1m ²	Sample No 06/B/8026/168 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Laundry Main Room Pipe debris	Asbestos Yes Type Chrysotile (White)
Material Type Lagging	Quantity <1m ²	Sample No 06/B/8026/169 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Laundry Rope to laundry equipment	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Rope	Quantity 2m	Sample No As 06/B/8026/58 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Laundry Red Pipe Lagging	Asbestos Type	Yes, Strongly presumed Chrysotile (White) Amosite (Brown)
Material Type	Lagging	Quantity	3m	Sample No As 06/B/8026/167
				Survey Date 24.04 - 29.06.06
				Date of Report 18.08.06
				Surveyor(s) [REDACTED]


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Laundry Electrics	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Rope	Quantity 1m ²	Sample No As 06/B/8026/22 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Laundry Rope gasket to dryer	Asbestos Yes Type Chrysotile (White)
Material Type Rope	Quantity 4m	Sample No 06/B/8026/170 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Lightwell adjacent Laundry Cement roof sheet		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	10m ²	Sample No	As 06/B/8026/126
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Lightwell adjacent Laundry Cement roof sheet debris	Asbestos Yes, Strongly Presumed Type Chrysotile (White)
Material Type Cement	Quantity 1m ²	Sample No 06/B/8026/126 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Laundry Caged area Tank insulation	Asbestos Yes Type Chrysotile (White) Crocidolite (Blue)
Material Type Lagging	Quantity 20m	Sample No 06/B/8026/171 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Laundry High level pipe Pipe lagging debris behind pipe	Asbestos Yes
Material Type Lagging		Quantity 12m ²	Type Amosite (Brown) Chrysotile (White)
			Sample No 06/B/8026/172
			Survey Date 24.04 - 29.06.06
			Date of Report 18.08.06
			Surveyor(s) 

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Door panel to door between Laundry & Laundry Store		Asbestos Type	Yes Chrysotile (White)
Material Type	Cement	Quantity	1m ²	Sample No	06/B/8026/173
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Laundry Foil corrugated paper pipe lagging		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Paper	Quantity	10m	Sample No	As 06/B/8026/50
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo WC adjacent Laundry Cistern	Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type Plastic	Quantity 1m ²	Sample No As 06/B/8026/5 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]	

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo External workshop electrics within cage	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	1m ²	Sample No As 06/B/8026/9 &22 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo External workshop electrics		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	1m ²	Sample No	As 06/B/8026/9 &22
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo External workshop cement debris (throughout)		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	10m ²	Sample No	As 06/B/8026/126
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Roof sheet in lean-to adjacent Laundry Store & Incinerator		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	40m ²	Sample No	As 06/B/8026/126
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Pipe lagging in lean-to adjacent Laundry Store & Incinerator	Asbestos Yes Type Chrysotile (White) Crocidolite (Blue)
Material Type Lagging	Quantity 10m	Sample No 06/B/8026/174 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Lagging debris in lean-to adjacent Laundry Store & Incinerator		Asbestos Type	Yes, Strongly Presumed Chrysotile (White) Crocidolite (Blue)
Material Type	Lagging	Quantity	<1m	Sample No	As 06/B/8026/174
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Incinerator Rope seal	Asbestos Yes, Strongly Presumed Type Chrysotile (White)
Material Type Rope	Quantity 4m	Sample No As 06/B/8026/22 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Store adjacent Incinerator Roof sheet		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Cement		Quantity 10m		Sample No	As 06/B/8026/126
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Laundry store Wall debris	Asbestos Yes Type Chrysotile (White)
Material Type Lagging	Quantity <1m	Sample No 06/B/8026/175 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo External Store adjacent Laundry Office Partition panel		Asbestos Type	 Yes, Strongly Presumed Chrysotile (White)
Material Type Cement		Quantity 4m ²		Sample No	As 06/B/8026/175
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET



Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Workshop adjacent Laundry Electrics	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	1m	Sample No As 06/B/8026/9 &22 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Derelict building adjacent Workshop Rope to pipework		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	1m	Sample No	As 06/B/8026/58
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Store adjacent Generator Cable wrap	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	2m	Sample No As 06/B/8026/43 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Store adjacent Generator Redundant fuses		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	<1m	Sample No	As 06/B/8026/9
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Derelict building adjacent Workshop Rope to pipework	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	<1m ²	Sample No As 06/B/8026/58 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Derelict building adjacent Workshop Rope to pipework		Asbestos Type	 Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	1m	Sample No	As 06/B/8026/58
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Workshop External debris		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Cement		Quantity 10m ²		Sample No	As 06/B/8026/126
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Workshop roof void Redundant Sink Pad		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Bitumen	Quantity	1m ²	Sample No	As 06/B/8026/64
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Mortuary House, Kitchen, Partition board to low level breakfast bar	Asbestos Yes Type Amosite (Brown)
Material Type Board	Quantity 2m ²	Sample No 06/B/8026/178 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Mortuary House kitchen, Skylight rope seal		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	4m	Sample No	As 06/B/8026/31
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Mortuary House kitchen, Sink Pad	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Bitumen	Quantity	<1m	Sample No As 06/B/8026/64
				Survey Date 24.04 - 29.06.06
				Date of Report 18.08.06
				Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Mortuary Fridge panels	Asbestos Yes, Strongly Presumed Type Chrysotile (White)
Material Type Cement	Quantity 80m ²	Sample No As 06/B/8026/161 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Mortuary W.C. Cistern	Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type Plastic	Quantity 1m ²	Sample No Survey Date Date of Report Surveyor(s)	As 06/B/8026/5 24.04 - 29.06.06 18.08.06

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Workshop adjacent Water Tank Tower Roof sheet	Asbestos Yes, Strongly Presumed	Type Chrysotile (White)
Material Type Cement	Quantity 100m ²	Sample No As 06/B/8026/126 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) 	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES	Position of Sample/Photo Workshop adjacent Water Tank Tower Undercroft Pipe Lagging (presumed throughout)	Asbestos Yes, Strongly Presumed Type Chrysotile (White) Crocidolite (Blue)
Material Lagging Type	Quantity >100m	Sample No As 06/B/8026/174 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Remote store to rear of Water Tank Tower Roof Sheet		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	40m ²	Sample No	As 06/B/8026/126
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Remote store to rear of Water Tank Tower Gasket debris	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Gasket	Quantity	<1m ²	Sample No As 06/B/8026/180 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Water Tower Corrugated lagging to Outtake Pipes		Asbestos Type	Yes Chrysotile (White)
Material Type	Paper	Quantity	1m ²	Sample No	06/B/8026/176
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Water Tower Debris to Outtake Pipes	Asbestos Yes Type Chrysotile (White)	
Material Type Lagging	Quantity <1m ²	Sample No 06/B/8026/177 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Water Tower Courtyard, Foreman's Office Textured coating to ceiling		Asbestos Yes
Material Type Textured coating		Quantity 10m ²	Type Chrysotile (White)	
		Sample No 06/B/8026/179		
		Survey Date 24.04 - 29.06.06		
		Date of Report 18.08.06		
		Surveyor(s) 		

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulson, Surrey, CR5 3ES		Position of Sample/Photo Water Tower Courtyard, Workshops Wall Gasket material		Asbestos	Yes, Strongly Presumed
Material Type Gasket		Quantity 1m ²		Type	Chrysotile (White)
				Sample No	As 06/B/8026/180
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Water Tower Courtyard, Workshops Gasket material		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Gasket		Quantity 4m ²		Sample No	As 06/B/8026/180
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph




SURVEY INFORMATION SHEET

Location of Survey		Position of Sample/Photo		Asbestos	Yes
Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Water Tower Courtyard, Workshops Gasket material		Type	Chrysotile (White)
Material Type	Gasket	Quantity	4m ²	Sample No	06/B/8026/180
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Water Tower Courtyard, Workshops Gasket material		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Gasket	Quantity	1m ²	Sample No	As 06/B/8026/180
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Water Tower Courtyard Workshops, Electrics		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	1m ²	Sample No	As 06/B/8026/22
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Water Tower Courtyard Board debris outside workshops	Asbestos Yes Type Amosite (Brown)
Material Type Board	Quantity 1m	Sample No 06/B/8026/181 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Water Tower Courtyard ECB Roof Upstand		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Cement		Quantity 4m ²		Sample No	As 06/B/8026/147
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Miscellaneous

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Water Tank Tower Electrics	Asbestos Yes, Strongly Presumed Type Chrysotile (White)
Material Type Rope	Quantity 2m	Sample No As 06/B/8026/9 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Water Tank Tower Office Ceiling	Asbestos Yes Type Amosite (Brown)
Material Type Board	Quantity 10m ²	Sample No 06/B/8026/224 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]


Photograph



SURVEY INFORMATION SHEET



Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Water Tank Tower Pipe Lagging (presumed throughout)		Asbestos Type	Yes, Strongly Presumed Chrysotile (White) Amosite (Brown)
Material Type Lagging		Quantity 1m ²		Sample No	As 06/B/8026/216
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Water Tank Tower Undercroft Lagging		Asbestos Type	Yes, Strongly Presumed Amosite (Brown) Chrysotile (White)
Material Type	Lagging	Quantity	1m ²	Sample No	As 06/B/8026/216
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital Coulsdon Surrey CR5 3ES		Position of Sample/Photo Bricked Up Garage adjacent Water Tower Debris to floor (noted throughout area)		Asbestos Type	Yes, Strongly Presumed Amosite (brown) Chrysotile (white)
Material Type	Board	Quantity	Approx 4m ²	Sample No	As 06/B/8026/130
				Survey Date	04/03/07
				Date of Report	13/03/07
				Surveyor(s)	

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital Coulson Surrey CR5 3ES		Position of Sample/Photo Bricked Up Garage adjacent Water Tower Redundant AIB Sheets (noted throughout area)		Asbestos Type	Yes, Strongly Presumed Amosite (brown) Chrysotile (white)
Material Type	Board	Quantity	20m ²	Sample No	As 06/B/8026/130
				Survey Date	04/03/07
				Date of Report	13/03/07
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital Coulsdon Surrey CR5 3ES		Position of Sample/Photo Bricked Up Garage adjacent Water Tower Redundant Flue Pipes (noted throughout area)		Asbestos Type	Yes, Strongly Presumed Chrysotile (white)
Material Type	Cement	Quantity	10m	Sample No	As 06/B/8026/20
				Survey Date	04/03/07
				Date of Report	13/03/07
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital Coulsdon Surrey CR5 3ES		Position of Sample/Photo Bricked Up Garage adjacent Water Tower Store Room High Level Pipe Lagging		Asbestos Type	Yes, Strongly Presumed Amosite (brown) Chrysotile (white)
Material Type	Lagging	Quantity	12m	Sample No	As 06/B/8026/219
				Survey Date	04/03/07
				Date of Report	13/03/07
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital Coulsdon Surrey CR5 3ES		Position of Sample/Photo Bricked Up Garage adjacent Water Tower Store room Redundant sheets (noted throughout)		Asbestos Type	Yes, Strongly Presumed Chrysotile (white)
Material Type	Cement	Quantity	4m ²	Sample No Survey Date Date of Report Surveyor(s)	As 06/B/8026/20 04/03/07 13/03/07

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital Coulsdon Surrey CR5 3ES		Position of Sample/Photo Bricked Up Garage adjacent Water Tower Store room adjacent corridor High Level pipe lagging		Asbestos Type	Yes, Strongly Presumed Amosite (brown) Chrysotile (white)
Material Type	Lagging	Quantity	10m	Sample No	As 06/B/8026/219
				Survey Date	04/03/07
				Date of Report	13/03/07
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital Coulsdon Surrey CR5 3ES		Position of Sample/Photo Bricked Up Garage adjacent Water Tower Ceiling to cupboard adjacent door to corridor		Asbestos Type	Yes, Strongly Presumed Chrysotile (white)
Material Type	Cement	Quantity	10m ²	Sample No	As 06/B/8026/20
				Survey Date	04/03/07
				Date of Report	13/03/07
				Surveyor(s)	

Photograph




SURVEY INFORMATION SHEET

Boiler House

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Boiler House Profiled Roof Sheet		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Cement		Quantity 400m ²		Sample No	As 06/B/8026/126
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Boiler House Store, Redundant Crane valve	Asbestos Yes Type Chrysotile (White)
Material Type Gasket	Quantity <1m ²	Sample No 06/B/8026/182 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Boiler House Door panel,		Asbestos Yes
Material Type Board		Quantity 1m ²		Type Amosite (Brown)
				Sample No 06/B/8026/183
				Survey Date 24.04 - 29.06.06
				Date of Report 18.08.06
				Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Boiler House Door panel debris		Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type	Board	Quantity	<1m	Sample No	As 06/B/8026/183
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Boiler House Roof Debris	Asbestos Yes Type Chrysotile (White)
Material Type Cement	Quantity 1m ²	Sample No 06/B/8026/184 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Boiler House Tank Room, Gaiter to tank (X4),		Asbestos Yes
Material Type Rope		Quantity 8m ²		Type Chrysotile (White)
				Sample No 06/B/8026/185
				Survey Date 24.04 - 29.06.06
				Date of Report 18.08.06
				Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Boiler Room Tank Room Main Tank Lagging		Asbestos	Yes
Material Type Lagging		Quantity 100m ²		Type	Chrysotile (White) Amosite (Brown)
				Sample No	06/B/8026/186
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Boiler House Tank Room, Tank (X4) Lagging		Asbestos Yes
Material Type Lagging		Quantity 80m ²		Type Chrysotile (White)
				Sample No 06/B/8026/187
				Survey Date 24.04 - 29.06.06
				Date of Report 18.08.06
				Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Boiler Room Pipe Lagging		Asbestos Yes
Material Type Lagging		Quantity 400m		Type Chrysotile (White) Amosite (Brown)
				Sample No 06/B/8026/188
				Survey Date 24.04 - 29.06.06
				Date of Report 18.08.06
				Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Boiler Room Tank Room Floor beneath tank Lagging debris (presumed throughout)		Asbestos Yes
Material Type Lagging		Quantity 1m ²		Type Chrysotile (White) Amosite (Brown)
				Sample No 06/B/8026/189
				Survey Date 24.04 - 29.06.06
				Date of Report 18.08.06
				Surveyor(s) [REDACTED]


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Boiler Room Electrics		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	1m ²	Sample No	As 06/B/8026/22
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Boiler House Redundant Gaskets		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Gasket	Quantity	1m ²	Sample No	As 06/B/8026/180
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Boiler Room W.C. Cistern		Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type	Plastic	Quantity	1m ²	Sample No	As 06/B/8026/5
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Boiler House Sink Pad		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Bitumen	Quantity	<1m ²	Sample No	As 06/B/8026/64
				Survey Date	24.04 – 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Oil Tank	Asbestos None Detected Type N/A
Material Type Bitumen	Quantity <1m ²	Sample No 06/B/8026/190 Survey Date 24.04 – 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph Corrupted



SURVEY INFORMATION SHEET

John Hutchinson Centre

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo John Hutchinson Centre Cement under metal duct cover	Asbestos Yes Type Chrysotile (White)
Material Type Cement	Quantity 10m ²	Sample No 06/B/8026/191 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo John Hutchinson Centre W.C. Cistern	Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type	Plastic	Quantity	1m	Sample No As 06/B/8026/5
				Survey Date 24.04 - 29.06.06
				Date of Report 18.08.06
				Surveyor(s) 

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo John Hutchinson Centre Partition wall panel	Asbestos None Detected	Type N/A
Material Type Plaster	Quantity 1m ²	Sample No 06/B/8026/192 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) 	

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo John Hutchinson Centre Office wall panel	Asbestos Yes, Strongly Presumed Type Chrysotile (White)
Material Type Cement	Quantity <1m ²	Sample No As 06/B/8026/195 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo John Hutchinson Centre Bunny Boiler & Flue pipe		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	1m	Sample No	As 06/B/8026/154
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo John Hutchinson Centre Ceiling panel to flat roofed room		Asbestos Yes
Material Type Board		Quantity 60m ²		Type Chrysotile (White) Amosite (Brown)
				Sample No 06/B/8026/193
				Survey Date 24.04 - 29.06.06
				Date of Report 18.08.06
				Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo John Hutchinson Centre Roof felt, flat roofed room		Asbestos Type	None Detected N/A
Material Type	Bitumen	Quantity	10m ²	Sample No	06/B/8026/194
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo John Hutchinson Centre Cement wall panels	Asbestos Yes Type Chrysotile (White)
Material Type Cement	Quantity 10m ²	Sample No 06/B/8026/195 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo John Hutchinson Centre Store Room Ceiling Panel		Asbestos Type	Yes, Strongly Presumed Chrysotile (White) Amosite (Brown)
Material Type	Board	Quantity	1m ²	Sample No	As 06/B/8026/193
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo John Hutchinson Centre Corridor wall panels (internal & external)		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Cement		Quantity 10m ²		Sample No	As 06/B/8026/195
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo John Hutchinson Centre Stair surround panels		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	4m ²	Sample No	As 06/B/8026/195
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo John Hutchinson Centre Main Hall Skylight rope seal		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Rope		Quantity 100m	Sample No As 06/B/8026/31		
			Survey Date 24.04 - 29.06.06		
			Date of Report 18.08.06		
			Surveyor(s) [REDACTED]		

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo John Hutchinson Centre Wall Panels adjacent conveyor	Asbestos Yes, Strongly Presumed Type Chrysotile (White)
Material Type Cement	Quantity 1m ²	Sample No As 06/B/8026/195 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES	Position of Sample/Photo John Hutchinson Centre External wall panels	Asbestos Yes, Strongly Presumed Type Chrysotile (White)
Material Type Cement	Quantity 6m ²	Sample No As 06/B/8026/126 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo John Hutchinson Centre External Garage Corrugated Roof sheet		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	10m ²	Sample No	As 06/B/8026/126
				Survey Date	24.04 – 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Nurses Accommodation Block

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES	Position of Sample/Photo Nurses Block, Middle Annex, First Floor Kitchen Cement panel	Asbestos Yes Type Amosite (Brown)
Material Type Board	Quantity <1m ²	Sample No 06/B/8026/196 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Nurses Block, Middle Annex First Floor Kitchen Sink Pad		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Bitumen	Quantity	<1m	Sample No	As 06/B/8026/64
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Middle Annex, Nurses Block W.C Cistern		Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type	Plastic	Quantity	1m	Sample No	As 06/B/8026/5
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Nurses Block, Middle Annex, Black stair nosing		Asbestos Yes
Material Type Vinyl		Quantity 14m		Type Chrysotile (White)
				Sample No 06/B/8026/197
				Survey Date 24.04 - 29.06.06
				Date of Report 18.08.06
				Surveyor(s) [REDACTED]


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Nurses Block, Middle Annex, Corridor wall electrics	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	<1m ²	Sample No As 06/B/8026/9 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Nurses Block, Middle Annex, Electric Cupboard		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	<1m ²	Sample No	As 06/B/8026/9
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES	Position of Sample/Photo Nurses Block, Middle Annex, Ground Floor, Wall panel to electric cupboard	Asbestos Type	Yes Amosite (Brown)
Material Type Board	Quantity 2m	Sample No Survey Date Date of Report Surveyor(s)	06/B/8026/198 24.04 - 29.06.06 18.08.06 


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Nurses Block, Middle Annex, W.C, Redundant flue pipe		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	<1m	Sample No	As 06/B/8026/154
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey		Position of Sample/Photo	Asbestos	Yes, Strongly Presumed	
Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Nurses Block, Middle Annex, Ground floor cupboard Wall Panel	Type	Amosite (Brown)	
Material Type	Board	Quantity	2m ²	Sample No	As 06/B/8026/198
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
			Surveyor(s)		


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Nurses Block, Middle Annex, Ground floor W.C. Redundant Flue pipe		Asbestos Type	 Yes, Strongly Presumed Chrysotile (White)
Material Type Cement		Quantity <1m		Sample No	As 06/B/8026/154
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulson, Surrey, CR5 3ES		Position of Sample/Photo Nurses Block, Rear Annex, Electrics	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	<1m ²	Sample No As 06/B/8026/9 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]


Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Nurses Block, Rear Annex, Electric cupboard Wall panel	Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type Board	Quantity 2m ²	Sample No As 06/B/8026/198 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]	

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Nurses Block, Rear Annex, W.C Bunny Boiler Flue and Internal Panels		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	1m	Sample No	As 06/B/8026/154
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Nurses Block, Rear Annex, Cupboard Wall Panel		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Plastic	Quantity	2m ²	Sample No	As 06/B/8026/
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Nurses Block, Rear Annex, W.C Bunny Boiler	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Cement	Quantity 1m	Sample No As 06/B/8026/154 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Nurses Block, Rear Annex, Corridor Electrics	Asbestos Yes, Strongly Presumed	Type Chrysotile (White)
Material Type Rope	Quantity <1m ²	Sample No As 06/B/8026/9	Survey Date 24.04 - 29.06.06
		Date of Report 18.08.06	Surveyor(s)


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Main Nurses Block, Second Floor, Domestic Cupboards in Corridor (X2), Pipe lagging (noted to all floors)		Asbestos Type	Yes, Strongly Presumed Chrysotile (White) Crocidolite (Blue)
Material Type	Lagging	Quantity	3m per cupboard X2 cupboards per floor	Sample No Survey Date Date of Report Surveyor(s)	As 06/B/8026/200 24.04 - 29.06.06 18.08.06 [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Main Nurses Block Stair Nosing		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Vinyl	Quantity	200m	Sample No	As 06/B/8026/197
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Main Nurses Block Bunny Boiler (X3)	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	2m	Sample No As 06/B/8026/154 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Main Nurses Block Bunny Boiler (X3)		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	2m	Sample No	As 06/B/8026/154
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Main Nurses Block Ironing Board Panel	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	<1m ²	Sample No As 06/B/8026/20 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Main Nurses Block Loft Lobby Pipe lagging	<table style="width: 100%;"> <tr> <td style="width: 30%;">Asbestos</td> <td>Yes</td> </tr> <tr> <td>Type</td> <td>Chrysotile (White) Crocidolite (Blue) Amosite (Brown)</td> </tr> </table>	Asbestos	Yes	Type	Chrysotile (White) Crocidolite (Blue) Amosite (Brown)				
Asbestos	Yes									
Type	Chrysotile (White) Crocidolite (Blue) Amosite (Brown)									
Material Type Lagging	Quantity 10m	<table style="width: 100%;"> <tr> <td style="width: 30%;">Sample No</td> <td>06/B/8026/201</td> </tr> <tr> <td>Survey Date</td> <td>24.04 - 29.06.06</td> </tr> <tr> <td>Date of Report</td> <td>18.08.06</td> </tr> <tr> <td>Surveyor(s)</td> <td style="background-color: black; color: black;">[REDACTED]</td> </tr> </table>	Sample No	06/B/8026/201	Survey Date	24.04 - 29.06.06	Date of Report	18.08.06	Surveyor(s)	[REDACTED]
Sample No	06/B/8026/201									
Survey Date	24.04 - 29.06.06									
Date of Report	18.08.06									
Surveyor(s)	[REDACTED]									

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Main Nurses Block Loft, Door Panels (X2)	Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type	Board	Quantity 2m ²	Sample No	As 06/B/8026/196
			Survey Date	24.04 - 29.06.06
			Date of Report	18.08.06
			Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Main Nurses Block (LHS) Loft Pipe lagging		Asbestos Type	Yes, Strongly Presumed Chrysotile (White) Crocidolite (Blue) Amosite (Brown)
Material Type	Lagging	Quantity	100m	Sample No	As 06/B/8026/201
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Main Nurses Block (RHS) Loft Pipe lagging		Asbestos Type	Yes, Strongly Presumed Chrysotile (White) Crocidolite (Blue) Amosite (Brown)
Material Type	Lagging	Quantity	100m	Sample No	As 06/B/8026/201
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Nurses Block Rear Annex, Loft Sectional lagging & Flue pipes		Asbestos Type	Yes, Strongly Presumed Chrysotile (White) Amosite (Brown)
Material Type	Lagging & Cement	Quantity	20m	Sample No	As 06/B/8026/199
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Nurses Block, Rear Annex, Loft, Sectional lagging		Asbestos Type	Yes, Strongly Presumed Chrysotile (White) Amosite (Brown)
Material Type	Lagging	Quantity	20m	Sample No	As 06/B/8026/202
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Nurses Block, Rear Annex, Loft, Box of Sectional lagging		Asbestos Type	Yes, Strongly Presumed Chrysotile (White) Amosite (Brown)
Material Type	Lagging	Quantity	1m ²	Sample No	As 06/B/8026/202
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Nurses Block, Middle Annex, Loft Cement flue pipes (X2)		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	2m ²	Sample No	As 06/B/8026/154
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Nurses Block, Rear Annex, External Roof Soffit panels		Asbestos Type	Yes Chrysotile (White)
Material Type	Cement	Quantity	180m ²	Sample No	06/B/8026/203
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Main Nurses Block Basement boiler room, LHS Under floor duct (X6) Pipe lagging,	Asbestos Yes
Material Type Lagging		Quantity 60m ²	Type Chrysotile (White)
			Sample No 06/B/8026/204
			Survey Date 24.04 - 29.06.06
			Date of Report 18.08.06
			Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Main Nurses Block Basement boiler room, Main floor duct Pipe lagging,		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Lagging		Quantity 40m	Sample No As 06/B/8026/204		
			Survey Date 24.04 - 29.06.06		
			Date of Report 18.08.06		
			Surveyor(s) 		

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Main Nurses Block Basement boiler room, Pipe lagging,	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Lagging	Quantity 100m		Sample No	As 06/B/8026/204
			Survey Date	24.04 - 29.06.06
			Date of Report	18.08.06
			Surveyor(s)	

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Main Nurses Block Basement boiler room, Tank Pipe lagging		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Lagging	Quantity	20m ²	Sample No	As 06/B/8026/204
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Main Nurses Block Store adjacent Basement Boiler room, Pipe lagging		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Lagging		Quantity 100m ²	Sample No As 06/B/8026/204		
			Survey Date 24.04 - 29.06.06		
			Date of Report 18.08.06		
			Surveyor(s) 		

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulson, Surrey, CR5 3ES		Position of Sample/Photo Main Nurses Block Basement boiler room, Main duct adjacent entrance Pipe lagging,		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Lagging Type		Quantity 40m		Sample No	As 06/B/8026/204
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Main Nurses Block Basement boiler room, RHS Under floor duct (X6) Pipe lagging,		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Lagging		Quantity 60m		Sample No	As 06/B/8026/205
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Nurses Block, Middle Annex, Boiler room, Pipe lagging	<table style="width: 100%;"> <tr> <td style="width: 50%;">Asbestos</td> <td>Yes</td> </tr> <tr> <td>Type</td> <td>Chrysotile (White) Crocidolite (Blue)</td> </tr> </table>	Asbestos	Yes	Type	Chrysotile (White) Crocidolite (Blue)				
Asbestos	Yes									
Type	Chrysotile (White) Crocidolite (Blue)									
Material Type Lagging	Quantity 10m ²	<table style="width: 100%;"> <tr> <td style="width: 50%;">Sample No</td> <td>06/B/8026/227</td> </tr> <tr> <td>Survey Date</td> <td>24.04 - 29.06.06</td> </tr> <tr> <td>Date of Report</td> <td>18.08.06</td> </tr> <tr> <td>Surveyor(s)</td> <td style="background-color: black; color: black;">[REDACTED]</td> </tr> </table>	Sample No	06/B/8026/227	Survey Date	24.04 - 29.06.06	Date of Report	18.08.06	Surveyor(s)	[REDACTED]
Sample No	06/B/8026/227									
Survey Date	24.04 - 29.06.06									
Date of Report	18.08.06									
Surveyor(s)	[REDACTED]									


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Nurses Block, Middle Annex, Boiler room, Ceiling panels	Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type Board	Quantity 8m ²	Sample No As 06/B/8026/196 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s)	As 06/B/8026/196 24.04 - 29.06.06 18.08.06

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Nurses Block, Middle Annex, Boiler Room, Tank lagging		Asbestos Type	Yes, Strongly Presumed Chrysotile (White) Crocidolite (Blue)
Material Type	Lagging	Quantity	20m	Sample No	As 06/B/8026/200
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Nurses Block, Middle Annex, Boiler Room, Pipe lagging		Asbestos Type	Yes, Strongly Presumed Chrysotile (White) Crocidolite (Blue)
Material Type	Lagging	Quantity	20m	Sample No	As 06/B/8026/227
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Nurses Block, Middle Annex, Boiler Room, Pipe lagging debris		Asbestos Type	Yes, Strongly Presumed Chrysotile (White) Crocidolite (Blue)
Material Type Lagging		Quantity <1m ²		Sample No	As 06/B/8026/200
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Shed adjacent Main Nurses Block Roof tiles		Asbestos Yes
Material Type Cement		Quantity 60m ²		Type Chrysotile (White)
				Sample No 06/B/8026/205
				Survey Date 24.04 - 29.06.06
				Date of Report 18.08.06
				Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Shed adjacent Main Nurses Block Redundant roof sheet		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	1m ²	Sample No	As 06/B/8026/126
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Shed adjacent Main Nurses Block, AIB debris on ground by (throughout area)	Asbestos Yes
Material Type Board		Quantity <1m ²	Type Amosite (Brown)
		Sample No 06/B/8026/206	
		Survey Date 24.04 - 29.06.06	
		Date of Report 18.08.06	
		Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Shed adjacent Main Nurses Block, Roof tiles		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	60m ²	Sample No	As 06/B/8026/205
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Shed adjacent Main Nurses Block Partition Panels		Asbestos	Yes, Strongly Presumed
Material Type Board		Quantity 10m ²		Type	Amosite (Brown)
				Sample No	As 06/B/8026/205
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Garden Stores (X4) Roof		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Cement		Quantity 40m ²		Sample No	As 06/B/8026/126
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Garden Store Redundant panel behind tank	Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type	Board	Quantity	1m ²	Sample No As 06/B/8026/198 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Garden Outbuildings Corrugated Roof Sheet	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	40m ²	Sample No As 06/B/8026/126 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Gardeners Cottage Fireplace board	Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type	Board	Quantity	Sample No	As 06/B/8026/198
		<1m ²	Survey Date	24.04 - 29.06.06
			Date of Report	18.08.06
			Surveyor(s)	

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Gardeners Cottage Electrics		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	1m	Sample No	As 06/B/8026/22
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Gardeners Cottage Under stairs Electrics		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	1m	Sample No	As 06/B/8026/22
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Gardeners Cottage W.C. Cistern		Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type	Plastic	Quantity	1m	Sample No	As 06/B/8026/5
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Gardeners Cottage, Plant Room, Tank lagging		Asbestos Yes
				Type Chrysotile (White) Amosite (Brown)
Material Type Lagging	Quantity 10m ²	Sample No 06/B/8026/207		
		Survey Date 24.04 - 29.06.06		
		Date of Report 18.08.06		
		Surveyor(s)		

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Gardeners Cottage, Plant Room, Pipe lagging	Asbestos Yes Type Chrysotile (White) Amosite (Brown)
Material Type Lagging	Quantity 2m ²	Sample No 06/B/8026/207 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Pipe Residue, Courtyard corridor, Gardeners Cottage		Asbestos Type	None Detected N/A
Material Type	Lagging	Quantity	10m	Sample No	06/B/8026/208
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

North Lodge

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo North Lodge External porch panels	Asbestos Yes, Strongly Presumed Type Chrysotile (White)
Material Type Cement	Quantity 2m	Sample No As 06/B/8026/195 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo North Lodge External Flue pipes (X3)		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	3m	Sample No	As 06/B/8026/154
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo North Lodge W.C. Cistern		Asbestos Type	Yes, Strongly Presumed Amosite (Brown))
Material Type	Plastic	Quantity	1m ²	Sample No	As 06/B/8026/5
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo North Lodge Ground Floor Kitchen Boiler Flue pipe	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Cement	Quantity 1m	Sample No As 06/B/8026/154 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo North Lodge First Floor Kitchen Boiler Flue pipe		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	1m	Sample No	As 06/B/8026/154
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo North Lodge First Floor Kitchen electrics		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	1m	Sample No	As 06/B/8026/9
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo North Lodge Loft Redundant panels	Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type Board	Quantity 1m ²	Sample No Survey Date Date of Report Surveyor(s)	As 06/B/8026/224 24.04 - 29.06.06 18.08.06

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo North Lodge Loft flue pipe		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Cement	Quantity	<1m ²	Sample No	As 06/B/8026/154
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo North Lodge External Redundant flue pipe	Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Cement	Quantity <1m ²	Sample No As 06/B/8026/154 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]	

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Swimming Pool Block Changing Room Pink cement roof tiles		Asbestos Yes
Material Type Cement		Quantity 100m ²		Type Chrysotile (White)
				Sample No 06/B/8026/209
				Survey Date 24.04 - 29.06.06
				Date of Report 18.08.06
				Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Swimming Pool Changing Room W.C. Cistern		Asbestos Type	Yes, Strongly Presumed Amosite (Brown)
Material Type	Plastic	Quantity	1m ²	Sample No	As 06/B/8026/5
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Nurses Block Remote Plant Room Tank Lagging		Asbestos Type	Yes, Strongly Presumed Chrysotile (White) Amosite (Brown)
Material Type	Lagging	Quantity	10m ²	Sample No	As 06/B/8026/207
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Nurses Block Remote Plant Room Pipe Lagging		Asbestos Type	Yes, Strongly Presumed Chrysotile (White) Amosite (Brown)
Material Type Lagging		Quantity 20m		Sample No	As 06/B/8026/207
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Corridor adjacent Main Hall Room under corridor adjacent to Derelict Main Hall Sectional lagging	Asbestos Yes Type Chrysotile (White) Amosite (Brown)	
Material Type Lagging	Quantity 20m	Sample No 06/B/8026/210 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]	

Photograph



SURVEY INFORMATION SHEET

Underground Ducts

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Underground duct Main Pipe Room beneath store adjacent Water Tank Tower Pipe Lagging	Asbestos Type	Yes, Strongly Presumed Chrysotile (White) Amosite (Brown)
Material Type	Lagging	Quantity	400m	Sample No As 06/B/8026/210
				Survey Date 24.04 - 29.06.06
				Date of Report 18.08.06
				Surveyor(s) [REDACTED]


Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Underground Duct under Generator Room adjacent to Main Pipe Room Pipe Lagging debris	Asbestos Yes Type Chrysotile (White) Amosite (Brown)
Material Lagging Type	Quantity <1m	Sample No 06/B/8026/211 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Underground duct Pipe lagging, Duct under Generator Room		Asbestos Type	Yes, Strongly Presumed Chrysotile (White) Amosite (Brown)
Material Type	Lagging	Quantity	200m	Sample No	As 06/B/8026/211
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Underground duct Sectional Pipe lagging, Duct under generator room leading towards Kitchens	Asbestos Type	Yes, Strongly Presumed Amosite (Brown) Chrysotile (White)
Material Type Lagging	Quantity 200m	Sample No As 06/B/8026/211 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Underground duct Hard set Pipe lagging in Duct adjacent Generator Room	Asbestos Yes, Strongly Presumed	Type Chrysotile (White) Amosite (Brown)
Material Type Lagging	Quantity 10m ²	Sample No As 06/B/8026/211 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Underground duct Floor debris, corridor duct adjacent Zachery York Ward		Asbestos	None Detected
Material Type Debris		Quantity <1m ²		Type	N/A
				Sample No	06/B/8026/212
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Underground duct Pipe residue in corridor duct adjacent to Zachery Unwin Ward	<table style="width: 100%;"> <tr> <td style="width: 50%;">Asbestos</td> <td>Yes</td> </tr> <tr> <td>Type</td> <td>Chrysotile (White)</td> </tr> </table>	Asbestos	Yes	Type	Chrysotile (White)				
Asbestos	Yes									
Type	Chrysotile (White)									
Material Type Lagging	Quantity <1m	<table style="width: 100%;"> <tr> <td style="width: 50%;">Sample No</td> <td>06/B/8026/213</td> </tr> <tr> <td>Survey Date</td> <td>24.04 - 29.06.06</td> </tr> <tr> <td>Date of Report</td> <td>18.08.06</td> </tr> <tr> <td>Surveyor(s)</td> <td style="background-color: black; color: black;">[REDACTED]</td> </tr> </table>	Sample No	06/B/8026/213	Survey Date	24.04 - 29.06.06	Date of Report	18.08.06	Surveyor(s)	[REDACTED]
Sample No	06/B/8026/213									
Survey Date	24.04 - 29.06.06									
Date of Report	18.08.06									
Surveyor(s)	[REDACTED]									

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Underground duct Pipe debris in corridor duct adjacent Vanbrugh Vincent Ward		Asbestos Type	Yes Chrysotile (White)
Material Type	Lagging	Quantity	<1m ²	Sample No	06/B/8026/214
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Underground duct beneath Corridor adjacent Turner Floor Cement Debris	Asbestos Yes, Strongly Presumed	Type Chrysotile (White)
Material Type Cement	Quantity <1m	Sample No As 06/B/8026/20 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Underground duct beneath Corridor adjacent Turner Sectional Pipe Lagging	Asbestos Yes, Strongly Presumed Type Amosite (Brown) Chrysotile (White)
Material Type Lagging	Quantity 200m	Sample No As 06/B/8026/215 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Underground duct beneath Corridor adjacent Shaftesbury/Salter Sectional Lagging & Redundant sectional lagging	Asbestos Yes Type Chrysotile (White) Amosite (Brown)	
Material Type Lagging	Quantity 1m	Sample No 06/B/8026/215 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Underground duct plant room, adjacent Nightingale Ward Pipe lagging,	Asbestos Yes Type Chrysotile (White) Amosite (Brown)
Material Type Lagging	Quantity 100m ²	Sample No 06/B/8026/216 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Underground duct beneath Corridor adjacent Nightingale Pipe lagging	Asbestos Type Yes, Strongly Presumed Chrysotile (White) Amosite (Brown)
Material Type Lagging	Quantity 100m	Sample No As 06/B/8026/216	Survey Date 24.04 - 29.06.06
		Date of Report 18.08.06	Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulson, Surrey, CR5 3ES		Position of Sample/Photo Underground duct beneath Corridor adjacent Nightingale- Wren Pipe Lagging		Asbestos Type	Yes, Strongly Presumed Amosite (Brown) Chrysotile (White)
Material Type	Lagging	Quantity	1m ²	Sample No	As 06/B/8026/216
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Underground duct beneath Corridor adjacent Turner Hardset lagging adjacent MMMF lagging	Asbestos Yes, Strongly Presumed	Type Amosite (Brown) Chrysotile (White)
Material Type Lagging	Quantity 200m	Sample No As 06/B/8026/216 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) 	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Underground duct beneath Corridor adjacent Stores Pipe Lagging		Asbestos Type	Yes, Strongly Presumed Amosite (Brown) Chrysotile (White)
Material Type	Lagging	Quantity	200m	Sample No	As 06/B/8026/216
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulson, Surrey, CR5 3ES	Position of Sample/Photo Underground duct beneath east side corridor adjacent Kitchen Corrugated Foil paper lagging	Asbestos Yes Type Chrysotile (White)	
Material Type Paper lagging	Quantity 20m	Sample No 06/B/8026/217 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]	

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Underground duct beneath east side corridor adjacent Kitchen, Sectional Lagging adjacent MMMF lagging		Asbestos Type	Yes, Strongly Presumed Chrysotile (White) Amosite (Brown)
Material Type	Lagging	Quantity	1m ²	Sample No	As 06/B/8026/216
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Underground Corridor Duct Sectional Pipe lagging (presumed throughout)		Asbestos Type	Yes, Strongly Presumed Chrysotile (White) Amosite (Brown)
Material Type	Lagging	Quantity	1000m ²	Sample No	As 06/B/8026/216
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Underground duct beneath Corridor adjacent to Dentist Sectional lagging,	Asbestos Yes Type Crocidolite (Blue)
Material Type Lagging	Quantity 200m	Sample No 06/B/8026/218 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Underground duct beneath Corridor adjacent to Dentist Sectional lagging debris,	Asbestos Yes Type Chrysotile (White) Amosite (Brown)
Material Type Lagging	Quantity 2m	Sample No As 06/B/8026/219 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Underground duct Corridor Duct adjacent Ellis Asbestos Bags in partially bricked up void		Asbestos Type	Yes, Strongly Presumed Chrysotile (White) Amosite (Brown) Crocidolite (Blue)
Material Type	Lagging	Quantity	3m ²	Sample No	As 06/B/8026/218 & 219
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Underground duct Corridor duct adjacent Ellis Hard Set Lagging	Asbestos None Detected Type N/A
Material Type Lagging	Quantity 1m ²	Sample No 06/B/8026/220 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Underground duct leading to boiler block adjacent Faraday Sectional lagging,		Asbestos Type	Yes Amosite (Brown)
Material Type	Lagging	Quantity	10m	Sample No	06/B/8026/221
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Underground duct beneath Corridor adjacent Guy Ward, Asbestos Bags in partially bricked up void	Asbestos Type	Yes, Strongly Presumed Chrysotile (White) Amosite (Brown) Crocidolite (Blue)
Material Type	Lagging	Quantity	2m	Sample No As 06/B/8026/218 & 219 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) 


Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Underground duct beneath link corridor adjacent King Keats ward Sectional lagging		Asbestos Yes
Material Type Lagging		Quantity 200m		Type Chrysotile (White)
		Sample No 06/B/8026/222		
		Survey Date 24.04 - 29.06.06		
		Date of Report 18.08.06		
		Surveyor(s) [REDACTED]		

Photograph




SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulson, Surrey, CR5 3ES		Position of Sample/Photo Underground duct Adjacent Staff Wing Sectional pipe lagging		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Lagging	Quantity	200m	Sample No	As 06/B/8026/222
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Underground duct Adjacent Liggett/Lettsom Ward Sectional pipe lagging		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Rope	Quantity	200m ²	Sample No	As 06/B/8026/222
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Underground duct adjacent Liggett/Lettsom Ward Floor debris		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Lagging	Quantity	1m ²	Sample No	As 06/B/8026/222
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES		Position of Sample/Photo Underground duct Void adjacent Water Tower Lagging to pipe work		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Lagging	Quantity	200m	Sample No	As 06/B/8026/222
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Underground duct adjacent Water Tower Corrugated Foil lagging	Asbestos Yes, Strongly Presumed	Type Chrysotile (White)
Material Type Paper	Quantity 1m	Sample No As 06/B/8026/217 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) 	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Underground duct under Water Tower Corrugated Foil lagging debris		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type Paper		Quantity 1m ²		Sample No	As 06/B/8026/217
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulston, Surrey, CR5 3ES		Position of Sample/Photo Underground duct Void adjacent Water Tower Asbestos Waste Bags in void		Asbestos Type	Yes, Strongly Presumed Chrysotile (White) Crocidolite (Blue) Amosite (Brown)
Material Type	Lagging	Quantity	1m ²	Sample No	As 06/B/8026/218 & 219
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulson, Surrey, CR5 3ES		Position of Sample/Photo Underground duct plant room adjacent Nightingale Ward Asbestos Waste bags		Asbestos Type	Yes, Strongly Presumed Chrysotile (White)
Material Type	Lagging	Quantity <1m		Sample No	As 06/B/8026/218 & 219
				Survey Date	24.04 - 29.06.06
				Date of Report	18.08.06
				Surveyor(s)	

Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Underground duct plant room adjacent Nightingale Ward Floor Lagging debris	Asbestos Yes, Strongly Presumed	Type Amosite (Brown) Chrysotile (White)
Material Type Lagging	Quantity <1m	Sample No As 06/B/8026/219 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]	


Photograph



SURVEY INFORMATION SHEET

Location of Survey Cane Hill Hospital, Cane Hill, Coulsdon, Surrey, CR5 3ES	Position of Sample/Photo Underground duct beneath Corridor adjacent Kitchen Sectional Lagging	Asbestos Yes Type Amosite (Brown)
Material Type Lagging	Quantity 200m	Sample No 06B8026/223 Survey Date 24.04 - 29.06.06 Date of Report 18.08.06 Surveyor(s) [REDACTED]

Photograph




6.

APPENDICES

APPENDIX ONE

BULK ANALYSIS SHEETS



**Certificate of Analysis
for
Bulk Asbestos Identification**

Report No: 06/B/8026	Date: 18/07/06	Page: 1 of 9
-----------------------------	-----------------------	---------------------

Client name & address:

Strategic Risk Management
P.O. Box 167
Sandbach
Cheshire, CW11 3WG.

Date sampled: 24-27/04/06**Date received:** 02/05/06- 17/07/06**Date analysed:** 18/07/06**Site address:** Cane Hill Hospital,**Reference:****Sampled by:** T. Johnson, A. Alderson & B. Stockwell

No.	Origin/location of sample	Material *	Asbestos type
1	Reception Block, 1 st Room, Male Side, Lathe And Plaster To Walls	Textured Coating	None Detected
2	Reception Block, 1 st Room, Male Side, Bitumen Felt Under Wood Floor	Bitumen	None Detected
3	Reception Block, 1 st Room, Ground Floor, Male Side, Fire Heating Element	Board	None Detected
4	1 st Room, Male Side, Through To Reception Entrance, Panel Above Door	Fiberboard	None Detected
5	Reception Block, W.C, Cistern	Plastic	Amosite (Brown)
6	Reception Block, W.C	Plastic	None Detected
7	Reception Block, Stairs, Grey Vinyl Floor Sheet	Vinyl	None Detected
8	Reception Block, Stairs, Red Stair Nosing	Vinyl	None Detected
9	Reception Block, Male Side, Basement, Flash Pad	Rope	Chrysotile (White)
10	Reception Block, Basement, Vinyl Floor Sheet	Vinyl & Bitumen	None Detected
11	Reception Block, Basement, Sash Window Rope Cord	Rope	None Detected
12	Reception Block, Basement, Green Vinyl Floor Sheet	Vinyl	None Detected
13	Reception Block, Basement, Red Vinyl Floor Sheet	Vinyl	None Detected
14	Reception Block, 2 nd Floor, Male Side, Fireplace Plinth	Board	Amosite (Brown) Chrysotile (White)
15	Reception Block, Loft, Male Side, Pipe Lagging	Lagging	None Detected
16	Reception Block, 1 st Floor, Cement Debris	Cement	Chrysotile (White)
17	Reception Block, 1 st Floor, Door Panel	Board	None Detected
18	Reception Lobby, Sink Pad Redundant Unit	Bitumen	None Detected
19	Reception Block, Panel Behind Radiator in Room Next To Stairs To Basement	Cement	Chrysotile (White)
20	Reception, Female Side, Basement, Cement Fireplace Panel	Cement	Chrysotile (White)
21	Reception Block, Basement, Bitumen & Rope Sheath To Electrical Intake Cable	Bitumen Rope	None Detected
22	Basement, Female Side, Switchboard	Rope	Chrysotile (White)

NORMANDIE

ANALYTICAL SERVICES

The Innovation Centre Technology Drive, Indigo Science Park, Bridgend Mid Glamorgan CF31 3YA
Tel 01656 650330 Fax 01656 650339 e-mail anal@normandie.co.uk

Certificate of Analysis for Bulk Asbestos Identification

Report No: 06/B/8026	Date: 18/07/06	Page: 2 of 9
----------------------	----------------	--------------


23	Reception Block, Ground Floor, Female Side, Green Patterned Vinyl Floor	Vinyl	None Detected
24	Reception Block, Ground Floor, Front Room, Female Side, Shelf Above Radiator	Board	Amosite (Brown) Chrysotile (White)
25	Stairs, Female Side, Turquoise Floor Lino	Vinyl	None Detected
26	Stairs, Female Side, White Stair Nosing	Vinyl	None Detected
27	1 st Floor, Front Office, Female Side, Partition Panels	Board	Amosite (Brown) Chrysotile (White)
28	1 st Floor Lobby, Fuse Carrier	Paper	Chrysotile (White)
29	Corridor Adj Reception, Beige Floor Tiles	Vinyl & Bitumen	Chrysotile (White) Chrysotile (White)
30	Corridor Adj Reception Red Floor Tiles	Vinyl & Bitumen	Chrysotile (White) Chrysotile (White)
31	Corridor Adj Reception, Rope Seal To Skylights	Rope	Chrysotile (White)
32	Corridor Left, Adj Hall/Chapel, Pipe Lagging In Wall Void	Lagging	Chrysotile (White)
33	Fibre Board Paper Lining In Small Room Between Chapel And LHS Adj Corridor	Paper	Chrysotile (White)
34	2 nd Room, Cement Sheet In Floor Duct With Solid Floor Adj Left Hand Side Of Corridor	Cement	Chrysotile (White)
35	Library Landing, Fibre Board Ceiling	Paper on F/B	Chrysotile (White)
36	Floor Coating, Lopped Up Walls In Last Room Right Hand Side Of Left Hand Corridor	ceramic	None Detected
37	Corridor To The Back Of Chapel, Grey Floor Tiles	Vinyl & Bitumen	None Detected Chrysotile (White)
38	Corridor To The Back Of Chapel, Red Floor Tile	Vinyl & Bitumen	None Detected Chrysotile (White)
39	Corner Room, Left Hand And Back Corridor, Floor Coating	Ceramic	None Detected
40	Back Room Of 2 nd Room, Back Corridor To Chapel, Sink Coating	Bitumen	None Detected
41	Dispensary Room, Sink Pad	Bitumen	Chrysotile (White)
42	Admin Office, Roof Coating	Bitumen	None Detected
43	Vestry, Rope Cable To Ceiling Lights	Rope	Chrysotile (White)
44	Pipe Lagging, Covered Light Well, Next To Vestry	Lagging	Crocidolite (Blue) Amosite (Brown)
45	Chapel, Small Red Floor Tiles	Vinyl & Bitumen	Chrysotile (White) Chrysotile (White)
46	Chapel, Small Black Floor Tiles	Vinyl & Bitumen	Chrysotile (White) Chrysotile (White)
47	Chapel, Sellow Material To Organ	Paper/Cloth	None Detected
48	Chapel, Pipe Lagging Residue In Undercroft	Lagging	None Detected
49	Chapel, Paper Debris	Paper	None Detected
50	Olave Queens Ward - Undercroft - Foil Lagging	Lagging	Chrysotile (White)



**Certificate of Analysis
for
Bulk Asbestos Identification**

Report No: 06/B/8026	Date: 18/07/06	Page: 3 of 9
-----------------------------	-----------------------	---------------------

51	Olave Queens Ward – Undercroft – Lagging	Lagging	None Detected
52	Olave Queens Ward – Sectional Lagging To Undercroft Pipework debris	Lagging	Chrysotile (White) Amosite (Brown)
53	Olave Queens Ward – Undercroft – Sectional Pipe Lagging	Lagging	Chrysotile (White) Amosite (Brown)
54	Olave Queens Ward – Green Floor Tile In Second Room	Vinyl & Backing	None Detected Chrysotile (White)
55	Olave Queens Ward – Crimson Floor Tile	Vinyl	None Detected
56	Olave Queens Ward – Shires Toilet Cistern – Ground Floor	Plastic	None Detected
57	Olave Queens Ward – Light Brown Floor Tile	Vinyl	None Detected
58	Olave Queens Ward – Rope Wrap Lagging In Kitchen – Ground Floor	Rope	Chrysotile (White)
59	Olave Queens Ward – Cloth Wrap Lagging In Kitchen – Ground Floor	Lagging	Chrysotile (White)
60	Browning Blake Ward – Pink Floor Tile	Vinyl	None Detected
61	Browning Blake Ward – Radiator Panel – Rest Room	Board	Chrysotile (White)
62	Browning Blake Ward – Sink Paint – Kitchen Off Middle Corridor – Ground Floor	Bitumen/Paint	None Detected
63	Browning Blake Ward – Grey Floor Tile	Vinyl/Bitumen	Chrysotile (White) Chrysotile (White)
64	Browning Blake Ward – Sink Pad – First Floor	Bitumen	Chrysotile (White)
65	Olave Queens Ward – Plug To Metal Riser In Forward Room – Ground Floor	Board	Amosite (Brown) Chrysotile (White)
66	Olave Queens Ward – Rope Wrap To Pipe In Undercroft Stores	Rope	None Detected
67	Olave Queens Ward – Undercroft Stores – Gasket	Gasket	None Detected
68	Browning Blake Ward – Bitumen On Fibreboard In High Heater Unit	Bitumen	None Detected
69	Blue Pipe Lagging In Calorifier Room Adjacent To Reception Block	Lagging	Amosite (Brown)
70	Floor Debris By Doorway – Calorifier Room	Lagging	Amosite (Brown)
71	Gasket To Pipework In Calorifier Room Adjacent To Reception Block	Gasket	Chrysotile (White)
72	Gaiter Material In Calorifier Room Adjacent To Reception Block	Rope/Lagging	Amosite (Brown) Chrysotile (White)
73	Calorifier Room Adjacent Reception – Red Pipe Lagging	Lagging	Amosite (Brown) Chrysotile (White)
74	Calorifier Room Adjacent Reception – Small Blue Tank Lagging	Lagging	Amosite (Brown) Chrysotile (White)
75	Olave Queens Ward – Room In Corridor – Door Panel	Cement	Chrysotile (White)



**Certificate of Analysis
for
Bulk Asbestos Identification**

Report No: 06/B/8026	Date: 18/07/06	Page: 4 of 9
-----------------------------	-----------------------	---------------------


76	Olave Queens Ward – Beige Floor Tile In Corner Office Of Corridor To Rear Of Ward	Vinyl	None Detected
77	Olave Queens Ward – Paper Foil Lagging Undercroft Middle Corridor	Lagging	Chrysotile (White))
78	Olave Queens Ward – Riser Panel – End Room Of Corridor To Rear Of Ward	Board	Amosite (Brown)
79	Browning Blake Ward – Lagging Debris Under Floor Duct – Corridor To Rear Of Ward	Lagging	None Detected
80	Andrewes First Ward – Debris From Floor Duct	Debris	None Detected
81	Andrewes First Ward – Plaster Ceiling	Textured Coating	None Detected
82	Andrewes Ward, First Floor W.C. Floor	Cement	None Detected
83	Andrewes Ward, First Floor Ward	Vinyl	None Detected
84	Corridor Room Adjacent Pugin/Paxton, Cupboard Adjacent Fireplace, Rdt Panel	Board	Chrysotile (White)
85	Pugin/Paxton, Metal Riser Rawl Plugs	Rope	Chrysotile (White)
86	Pugin/Paxton, Ground W.C. Ceiling Tiles	Board	None Detected
87	Pugin/Paxton Ground W.C Cistern	Plastic	None Detected
88	Pugin/Paxton, First Floor Kitchen, Pipe Cloth Wrap	Rope	Chrysotile (White)
89	Pugin/Paxton, First Floor Corner Office Floor	Vinyl	None Detected
90	Corridor Adjacent Pugin/Paxton, Wall	Textured Coating	None Detected
91	Corridor Adjacent Pugin/Paxton Floor Tile	Vinyl & Bitumen	Chrysotile (White) Chrysotile (White)
92	Corridor Adjacent Pugin/Paxton Floor Tile	Vinyl & Bitumen	Chrysotile (White) Chrysotile (White)
93	Corridor Adjacent Pugin/Paxton Floor Tile	Vinyl & Bitumen	Chrysotile (White) Chrysotile (White)
94	Ruskin/Rosetti Ground Kitchen Riser Panel	Board	Chrysotile (White)
95	Corridor Adjacent Ruskin/Rosetti Floor Bitumen	Bitumen	None Detected
96	Ruskin/Rosetti Undercroft Pipe Residue	Debris	None Detected
97	Corridor Adjacent Pugin/Paxton Ceiling	Plaster	None Detected
98	Corridor Adjacent Shaftesbury/Salter Floor Tile	Vinyl & Bitumen	Chrysotile (White) Chrysotile (White)
99	Corridor Adjacent Shaftesbury/Salter Floor Tile	Vinyl & Bitumen	Chrysotile (White) Chrysotile (White)
100	Corridor Adjacent Shaftesbury/Salter Floor Tile	Vinyl & Bitumen	Chrysotile (White) Chrysotile (White)
101	Corridor Adjacent Shaftesbury/Salter Floor Tile	Vinyl & Bitumen	Chrysotile (White) Chrysotile (White)
102	Shaftesbury/Salter Undercroft Debris	Debris	Amosite (Brown) Chrysotile (White)
103	Shaftesbury/Salter Ground W.C Lobby Wall Panel	Cement	Chrysotile (White)



**Certificate of Analysis
for
Bulk Asbestos Identification**

Report No: 06/B/8026 **Date:** 18/07/06 **Page:** 5 of 9


104	Shaftesbury/Salter Ground Floor Office Wall Panel	Board	Amosite (Brown)
105	Shaftesbury/Salter, Undercroft, Debris	Lagging & Debris	None Detected
106	Shaftesbury/Salter, Fuse Box Shelf	Cement	Chrysotile (White)
107	Vanburgh/Vincent Undercroft Debris	Debris	None Detected
108	Vanburgh/Vincent Corridor Wall	Textured Coating	None Detected
109	Turner Ward First Floor Bunny Boiler Internal Panel	Cement	Chrysotile (White)
110	Center Longitudinal Tunnel Wall Water Pipe	Bitumen Lagging	None Detected
111	Center Longitudinal Tunnel Fuse Box Flashguard	Rope	Chrysotile (White)
112	First Lateral Tunnel Refrigeration Unit Seal	Sealant	None Detected
113	Redundant AIB Sheet in S.L. Tunnel	AIB	Amosite (Brown)
114	South Longitudinal Tunnel Redundant Sheets	Board	Chrysotile (White)
115	South Longitudinal Tunnel Redundant Sheets	Cement	Chrysotile (White)
116	South Longitudinal Tunnel Cement Sheets	Cement	Chrysotile (White)
117	Vanburgh/Vincent Link Corridor Ceiling	Plaster	None Detected
118	Vanburgh/Vincent Kitchen Door Surround	Plaster	None Detected
119	Vanburgh/Vincent W.C. Link Corridor Wall Panel	Board	Amosite (Brown) Chrysotile (White)
120	Vanburgh/Vincent Ground Floor Tile	Vinyl	None Detected
121	Vanburgh/Vincent Undercroft	Rope Debris	None Detected
122	Vanburgh/Vincent Undercroft	Lagging Debris	None Detected
123	Wren/Wesley Undercroft Debris	Lagging Debris	Crocidolite (Blue) Amosite (Brown) Chrysotile (White)
124	Wren/Wesley Ward Door Beading	Board	None Detected
125	Zachary York Floor Tile	Vinyl & Bitumen	Chrysotile (White) Chrysotile (White)
126	Workshop First Floor Roof	Cement	Chrysotile (White)
127	Workshop Accommodation Roof Felt	Felt	None Detected
128	Workshop Accommodation Dauntless Dolphin W.C. Cistern	Plastic	Amosite (Brown)
129	Workshop Garage Internal Panels	Cement	Chrysotile (White)
130	Nightingale First Floor Consultation Room Window Infill Panel	Board	Amosite (Brown) Chrysotile (White)
131	Nightingale Undercroft Debris	Lagging & Debris	Crocidolite (Blue) Amosite (Brown) Chrysotile (White)
132	Stores Hall Pipe Lagging	Lagging	Amosite (Brown)
133	Calorifier Room Adjacent Faraday Pipe Lagging	Lagging	Amosite (Brown) Chrysotile (White)



**Certificate of Analysis
for
Bulk Asbestos Identification**

Report No: 06/B/8026	Date: 18/07/06	Page: 6 of 9
-----------------------------	-----------------------	---------------------

134	Calorifier Room Adjacent Faraday External Soffit	Cement	Chrysotile (White)
135	Sink paint, ground floor kitchen, Faraday Ward	Bitumen paint	None detected
136	Lagging debris, undercroft, Guy Ward	Lagging	Amosite (Brown)
137	Lagging to RH external pipe leading to undercroft, Harvard ward	Lagging	None detected
138	Lagging to LH external pipe leading to undercroft, Harvard ward	Lagging	None detected
139	Textured coating to support pillar, Harvard ward	Textured coating	None detected
140	Pipe residue, corridor undercroft, Harvard ward	Debris	None detected
141	Soffit board, outhouse adj to Guy ward	Board	Amosite (Brown) Chrysotile (White)
142	Roof felt, outhouse adj to Guy ward	Bitumen	None detected
143	Damp course, outhouse adj to Guy ward	Bitumen	None detected
144	Panel to hatch, lift motor room, King Keats ward	Board	None detected
145	Panel to hatch, lift motor room, Harvard ward	Board	Amosite (Brown) Chrysotile (White)
146	Textured coating to support pillar, Johnson ward	Textured coating	None detected
147	Upstand to skylight roof in sun room, ground floor, Johnson ward	Cement	Chrysotile (White)
148	Ceiling panels to sun room, Johnson ward	Cement	Chrysotile (White)
149	Fillet panel above windows above doors to cells, ground floor, Johnson ward	Board	None detected
150	Lagging debris on floor in boiler house adj to Johnson ward	Lagging	Amosite (Brown) Chrysotile (White)
151	Door panel, boiler block adjacent Johnson Jenner	Board	Amosite (brown) Chrysotile (White)
152	Red pipe lagging, boiler block adjacent Johnson Jenner	Lagging	Amosite (brown)
153	Panels in loft, nurses block adjacent King Keats	Board	Amosite (brown)
154	Cement sheet in bunny boiler, nurses block adjacent King Keats	Cement	Chrysotile (White)
155	Paper insert to pipe lagging, undercroft, Lidditt	Paper	Chrysotile (White)
156	Textured coating to pillars, 1 st floor, Lidditt	Textured coating	None detected
157	Sink paint, kitchen, ground floor, Lidditt	Bitumen	Chrysotile (White)
158	Cement panel under sideboard, kitchen, Art Therapy	Cement	Chrysotile (White)
159	Foil paper lagging, undercroft, Canteen	Paper	Chrysotile (White)
160	Radiator panel, catering hall, Canteen	Cement	Chrysotile (White)
161	Cement to fridge wall, Kitchen	Cement	Chrysotile (White)
162	Cement guttering, store, Kitchen	Cement	Chrysotile (White)
163	Cement wall panel, office, Laundry	Cement	Chrysotile (White)



**Certificate of Analysis
for
Bulk Asbestos Identification**

Report No: 06/B/8026	Date: 18/07/06	Page: 7 of 9
-----------------------------	-----------------------	---------------------

164	Foil paper lagging, small office in main room, Laundry	Paper	Chrysotile (White)
165	Paper under MMMF lagging, toilets, Laundry	Paper	Chrysotile (White)
166	Laundry WC window panel above boiler	Board	Amosite (Brown)
167	Red pipe lagging, main room, Laundry	Lagging	Chrysotile (White) Amosite (Brown)
168	Wall debris, main room, Laundry	Debris	Chrysotile (White)
169	Pipe debris, main room, Laundry	Lagging	Chrysotile (White)
170	Rope gasket to dryer, Laundry	Rope	Chrysotile (White)
171	Tank insulation, Laundry	Lagging	Chrysotile (White) Crocidolite (Blue)
172	Pipe lagging debris behind pipe, Laundry	Lagging	Chrysotile (White) Amosite (brown)
173	Door panel to door between Laundry & Laundry Store	Cement	Chrysotile (White)
174	Pipe lagging in lean-to adjacent Laundry Store	Lagging	Chrysotile (White) Crocidolite (Blue)
175	Wall residue, Laundry Store	Cement	Chrysotile (White)
176	Corrugated lagging, outtake pipes, Water Tower	Paper	Chrysotile (White)
177	Debris to outtake pipes, Water Tower	Lagging	Chrysotile (White)
178	Partition board, kitchen, Mortuary House	Board	Amosite (brown)
179	Textured coating to ceiling, Foremans Office, Water Tower Courtyard	Textured coating	Chrysotile (White)
180	Gasket material, workshops, Water Tower Courtyard	Gasket	Chrysotile (White)
181	Board debris outside workshops, Water Tower Courtyard	Board	Amosite (brown)
182	Crane valve gasket, Store, Boiler House	Gasket	Chrysotile (White)
183	Door panel, Boiler House	Board	Amosite (brown)
184	Roof sheet debris, Boiler House	Cement	Chrysotile (White)
185	Gutter to tank, Tank Room, Boiler House	Rope	Chrysotile (White)
186	Insulation, Tank adjacent Door, Tank Room, Boiler House	Lagging	Chrysotile (White) Amosite (brown)
187	Insulation, Tank adjacent wall, Tank Room, Boiler House	Lagging	Chrysotile (White)
188	Pipe lagging, Tank Room, Boiler House	Lagging	Chrysotile (White) Amosite (Brown)
189	Floor debris, Tank Room, Boiler House	Lagging	Chrysotile (White) Amosite (Brown)
190	Bitumen to external oil tanks, Boiler House	Bitumen	None Detected
191	Cement under metal duct cover, John Hutchinson Centre	Cement	Chrysotile (White)

NORMANDIE

ANALYTICAL SERVICES
The Innovation Centre Technology Drive, Bridgend Science Park, Bridgend Mid Glamorgan CF31 2NA
Tel 01656 660000 Facsimile 01656 660006 e-mail info@normandie.co.uk

Certificate of Analysis for Bulk Asbestos Identification

Report No: 06/B/8026 Date: 18/07/06 Page: 8 of 9

192	Partition wall panel, John Hutchinson Centre	Board	None Detected
193	Ceiling panel to flat roofed room, John Hutchinson Centre	Board	Chrysotile (White) Amosite (brown)
194	Roof felt, flat roofed room, John Hutchinson Centre	Bitumen	None Detected
195	Cement wall panels, John Hutchinson Centre	Cement	Chrysotile (White)
196	Cement panel, 1 st floor kitchen, Middle Annex, Nurses Block	Board	Amosite (Brown)
197	Black stair nosing, Middle Annex, Nurses Block	Vinyl	Chrysotile (White)
198	Wall panel to electric cupboard, ground floor, Middle Annex, Nurses Block	Board	Amosite (Brown)
199	Pipe lagging, riser behind sink, end bedroom, 3 rd floor, Main Nurses Block	Lagging	Chrysotile (White) Amosite (brown)
200	Pipe lagging, domestic cupboard in corridor, 3 rd floor, Main Nurses Block	Lagging	Chrysotile (White) Crocidolite (Blue)
201	Pipe lagging, Loft, Main Nurses Block	Lagging	Chrysotile (White) Crocidolite (Blue) Amosite (Brown)
202	Sectional lagging, Rear Annex, Nurses Block	Lagging	Amosite (Brown) Chrysotile (White)
203	Soffit panel, Rear Annex, Nurses Block	Cement	Chrysotile (White)
204	Pipe lagging, basement boiler room, Main Nurses Block	Lagging	Chrysotile (White)
205	Roof tiles, Shed adjacent Main Nurses Block	Cement	Chrysotile (White)
206	AlB debris on ground by Shed adjacent Main Nurses Block	Board	Amosite (Brown)
207	Pipe lagging, Plant Room, Gardeners Cottage	Lagging	Chrysotile (White) Amosite (Brown)
208	Pipe Residue, Courtyard corridor, Gardeners Cottage	Debris	None Detected
209	Pink cement roof tiles, Swimming Pool Block	Cement	Chrysotile (White)
210	Sectional lagging, room under corridor adjacent to Main Hall	Lagging	Chrysotile (White) Amosite (Brown)
211	Pipe lagging, Duct under generator room	Lagging	Chrysotile (White) Amosite (Brown)
212	Floor debris, corridor duct adjacent Zachery York	Debris	None Detected
213	Pipe residue, corridor duct adjacent Zachery Unwin	Lagging	Chrysotile (White)
214	Pipe residue, corridor duct adjacent Vanbrough Vincent	Debris	Chrysotile (White)
215	Sectional lagging, corridor duct adjacent Shaftsbury Salter	Lagging	Chrysotile (White) Amosite (Brown)



**Certificate of Analysis
for
Bulk Asbestos Identification**

Report No: 06/B/8026	Date: 18/07/06	Page: 9 of 9
-----------------------------	-----------------------	---------------------

216	Pipe lagging, plant room, adjacent Nightingale	Board	Chrysotile (White) Amosite (Brown)
217	Foil paper lagging, corridor duct east side adjacent kitchen	Paper	Chrysotile (White)
218	Sectional lagging, Corridor duct adjacent to dentist	Lagging	Crocidolite (Blue)
219	Floor debris, Corridor duct adjacent to dentist	Lagging	Chrysotile (White) Amosite (Brown)
220	Rough hardest lagging, corridor duct adjacent Ellis	Lagging	None Detected
221	Sectional lagging, duct to boiler block adjacent faraday	Lagging	Amosite (Brown)
222	Sectional lagging, corridor lagging adjacent king keats	Lagging	Chrysotile (White)
223	Sectional lagging, duct under kitchen	Lagging	Amosite (Brown)
224	A/B roof panels, ground floor, Water Tower	Board	Amosite (Brown)
225	A/B debris, loft, Rossetti	Board	Chrysotile (White) Amosite (Brown)
226	Pipe lagging, loft, Lidditt	Lagging	Chrysotile (White) Crocidolite (Blue)
227	Pipe lagging, boiler room, middle annex, nurses block	Lagging	Chrysotile (White) Crocidolite (Blue)

Normandie Analytical Services accept no responsibility for sampling activities undertaken by the client. All analysis is in accordance with HSG248/NASBIDM. The material description (*) shall be regarded as tentative and is not included in the UKAS Accreditation for this laboratory. Opinions and Interpretations are outside the scope of accreditation for this laboratory

Comments/details of sample preparation:

Signed (Analyst) [Signature] Print name [Redacted] Date...19/07/06
 Signed (Analyst) [Signature] Print name [Redacted] Date...19.7.06
 Approved..... [Signature] Print name [Redacted] Date...19.7.06



NASBIDR09

Issued Aug 05

Report Ends

6.

APPENDICES

APPENDIX TWO


SURVEY PLANS

Please note that these plans do not include the following surveyed areas:

**John Hutchington Centre
Main Nurses Block
Gardeners Cottage/Outbuildings
North Lodge
Swimming Pool**


6.

APPENDICES




6.

APPENDICES




6.

APPENDICES




6.

APPENDICES




6.

APPENDICES



6.

APPENDICES



Key

- - Contaminated Duct / Area - High Risk
- - Identified Contaminated Undercroft
- - NO Access
- - Floor Tiles

6. APPENDICES

KEY

-  = IDENTIFIED ASBESTOS
-  = STRONGLY PRESUMED ASBESTOS
-  = PRESUMED ASBESTOS
-  = IDENTIFIED NON-ASBESTOS

6.

APPENDICES

END OF REPORT