



Survey Type	Quality Level	Post-Processing	Location Accuracy		Supporting Data	
			Horizontal	Vertical		
D	Desktop utility Records Search	QL-D	-	Undefined	-	
C	Site Reconnaissance	QL-C	-	Undefined	A segment of utility whose location is demonstrated by visual reference to street furniture, topographical features or evidence of previous street works (reinstatement scar).	
B	Detection	QL-B4	No	Undefined	A utility segment which is suspected to exist but has not been detected and is therefore shown as an assumed route.	
		QL-B3	No	±500mm	Horizontal location only of the utility detected by one of the geophysical techniques used.	
		QL-B3P	Yes	Undefined (No reliable depth measurement possible)		
		QL-B2	No	±250mm or 40% of detected depth whichever is greater	Horizontal and vertical location of the utility detected by one of the geophysical techniques used.	
		QL-B2P	Yes	±40% of detected depth		
		QL-B1	No	±150mm or 15% of detected depth whichever is greater	Horizontal and vertical location of the utility detected by one of the geophysical techniques used.	
		QL-B1P	Yes	±15% of detected depth		
A	Verification	QL-A	-	±50mm	±25mm	Horizontal and vertical location of the top and/or bottom of the utility.